

ASS. REC. BY:

REF:

CT2/ 22001135/KP

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNC 73315

Yr Regn:

11.21

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Corolla

c.c

1797

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

15506

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZWE 211

606888

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModl: ☒ M / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

31/1/22

D.O.I.

14/2/2022

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/2

Work request for long day repair as parts not more than one month to reach SG.

18/3

1 Day @ 4500. Continued

red:8964.55;66%

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



Date: 04.02.2022

Vehicle No: SNC7331S

Model: TOYOTA COROLLA HYBRID GX

Chassis: ZWE2116068868

Reg.Year: 2021

Third Party Insurer:

CHINA TAIPING

Third Party Veh No:

SJR2012P

Date of Accident:

31.01.2022

Estimator:

KIT

Surveyor:

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID <i>839.50</i>	1	<i>R</i>	\$1,280.40
2	REAR BOOTLID "LOGO" EMBLEM <i>85.10</i>	1	<i>R</i>	\$100.10
3	REAR BOOTLID "COROLLA" EMBLEM	1	<i>R</i>	\$95.80
4	REAR BOOTLID "HYBRID" EMBLEM	1	<i>R</i>	\$96.40
5	REAR BOOTLID OUTER GARNISH	1	<i>R</i>	\$516.20
6	REAR BOOTLID TAILLAMP LH	1	<i>R</i>	\$297.30
7	REAR BOOTLID TAILLAMP RH	1	<i>R</i>	\$297.30
8	REAR BOOTLID MECHANISM LOCK	1	<i>R</i>	\$613.40
9	REAR BOOTLID INNER TRIM BOARD	1	<i>R</i>	\$272.60
10	REAR BOOTLID HINGE LH	1	<i>R</i>	\$116.10
11	REAR BOOTLID HINGE RH	1	<i>R</i>	\$116.10
12	REAR BOOTLID WEATHERSTRIP	1	<i>R</i>	\$307.40
13	REAR TAILLAMP OUTER LH	1	<i>R</i>	\$456.80
14	REAR TAILLAMP OUTER RH	1	<i>R</i>	\$456.80
15	REAR TAILLAMP OUTER LOWER BRACKET LH	1	<i>R</i>	\$145.70
16	REAR TAILLAMP OUTER LOWER BRACKET RH	1	<i>R</i>	\$145.70
17	REAR BUMPER <i>1218.30</i>	1	<i>R</i>	\$1,854.60
18	REAR BUMPER SIDE RETAINER LH	1	<i>R</i>	\$172.60
19	REAR BUMPER SIDE RETAINER RH	1	<i>R</i>	\$172.60
20	REAR BUMPER LOWER	1	<i>R</i>	\$375.80
21	REAR BUMPER TOW HOOK COVER	1	<i>R</i>	\$36.30
22	REAR BUMPER REFLECTOR LH	1	<i>R</i>	\$79.80
23	REAR BUMPER REFLECTOR RH	1	<i>R</i>	\$79.80
24	REAR END PANEL	1	<i>R</i>	\$896.10
25	REAR END PANEL INNER TOP GARNISH	1	<i>R</i>	\$371.20
26	REAR END PANEL LOCK STRIKER	1	<i>R</i>	\$47.90
27	REAR SPARE TYRE PANEL	1	<i>R</i>	\$1,081.70
28	REAR SPARE TYRE PANEL INNER TOP TOOLS SPONGE	1	<i>R</i>	\$372.70
29	REAR SPARE TYRE PANEL INNER TOP CARD BOARD	1	<i>R</i>	\$609.10
30	REAR EXHAUST SILENCER BOX	1	<i>R</i>	\$1,595.20
31	REAR EXHAUST TOP RUBBER MOUNTING	1	<i>R</i>	\$75.40
32	REAR EXHAUST TOP HEAT SHIELD	1	<i>R</i>	\$304.50
SUB TOTAL				\$13,439.40
LESS 25%				-\$3,359.85
PARTS TOTAL				\$10,079.55

### Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011





Date: 04.02.2022  
Vehicle No: SNC7331S  
Model: TOYOTA COROLLA HYBRID GX  
Chassis: ZWE2116068868  
Reg.Year: 2021

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SJR2012P  
Date of Accident: 31.01.2022  
Estimator: KIT  
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR NUMBER PLATE WITH HOLDER	1		Ref \$65.00
2	REAR BOOTLID INNER TRIM BOARD CLIPS	1		nn \$30.00
3	REAR BUMPER CLIPS	1		nn \$50.00
4	REAR BUMPER REVERSE SENSOR	1		Ref \$300.00
5	REAR END PANEL INNER TOP GARNISH CLIPS	1		nn \$20.00
S/N TOTAL				\$465.00

450  
X  
✓  
200/1  
—

## LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREA.

\$1,200.00

900

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA.

\$1,200.00

800

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00

50

TO DIAGNOSE FAULT CODE & RESET MEMORY.

nn \$120.00

X

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$200.00

60

TO CHECK WIRING & ELECTRICAL SYSTEM ETC.

\$100.00

20

LABOUR TOTAL \$2,920.00

KIT

TOTAL \$13,464.55

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be displayed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

#### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	305D
<b>Vehicle Details</b>	
Vehicle No.:	SNC73315
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Feb 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA HYBRID GX CVT
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	2ZR2L64155
Chassis No.:	ZWE2116068868
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$25,392.00
Original Registration Date:	12 Nov 2021
First Registration Date:	12 Nov 2021
Transfer Count:	0
Actual ARF Paid:	\$12,549.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Nov 2031
PARF Rebate Amount:	\$9,411.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	11 Nov 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$82,801.00
COE Rebate Amount:	\$80,914.00
<b>Total Rebate Amount:</b>	<b>\$90,325.00</b>

The information contained herein is correct as at 03 Feb 2022

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 03/02/2022 17:21 (SGT)  
Date of Accident ..... 31/01/2022 17:45 (SGT)  
Exact Location of Accident ..... Tampines Ave 2, Singapore  
Additional Location Information ..... TAMPINES AVENUE 2 NEARBY CATHOLIC CHURCH OF THE HOLY TRINITY  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SNC7331S

#### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... PROTESINGAPORE  
Company Reg No ..... 53323305D  
Email Address ..... JUBSTARSG@GMAIL.COM  
Mobile Phone No ..... (Phone) +65-87508831  
Alternative Phone No ..... (Home) +65-87508831

#### VEHICLE PARTICULARS

Manufacturer ..... Toyota  
Model ..... Corolla  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private hire  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private hire  
Transmission ..... Auto  
CC ..... 1600

#### INSURANCE COMPANY


Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... Yes  
Policy Number ..... 5114151142-02  
Cover Note Number ..... -

#### DRIVER

Name of Driver ..... CHUA HOK LAI RAYMOND

Vehicle Category .....	Private car
Name of Driver .....	HENRY GIAM TENG HIN
NRIC No .....	S0948327F
Contact Number .....	(Phone) +65-85111943
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	-
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	-

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 31/01/2022 @ 4:45 HOURS, I WAS TRAVELLING ALONG TAMPINES AVE 2 (NEARBY CATHOLIC CHURCH OF THE HOLY TRINITY). TRAFFIC LIGHT AHEAD TURN AMBER AND I BRAKED. SUDDENLY VEHICLE B: SJR2012P WAS UNABLE TO STOP IN TIME AND COLLIDED INTO MY VEHICLE A: SNC7331S REAR PORTION CAUSING DAMAGE. WE BOTH EXCHANGED OUR PARTICULARS.


DECLARATION



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Date & Time: 3/2/22



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: