

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Liu Chun Cheong

Date: 10 Feb 2022

Preliminary Advice

Vehicle No	: SML2396C	Accident Date	: 03/02/2022
Make	: MAZDA 3	Policy No.	: MPC21P00120600
Assignment Date	: 07/02/2022	Excess	: S\$750.00
Date of Inspection	: 08/02/2022	Est. Duration of Repair	: 7
Inspection At	: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01, KAKI BUKIT (SOUTH WING) SINGAPORE 415933		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 19,914.00
Revised Amount	:S\$ 7,943.20
Check Items (Estimated)	:S\$ 5,420.00
Total	:S\$ 13,363.20

Lump Sum Repair (estimate) :S\$ 10,700.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 17,500.00
COE / PARF Rebate	:S\$ 6,401.00
Salvage Value	:S\$

Margin for Repair

:S\$ 11,099.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.