

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

aim
Signature: _____
Date: _____

Automobile Integrated Management Pte Ltd

Co. & G.S.T. Reg no. 201605297G

Workshop: 23 Kaki Bukit Ave 4 #04-01 (South Wing) Singapore 415933

Email: automim.claim@gmail.com Tel: 9119 8371

Website: www.aimgarage.com.sg

ECICS OD

Xiao Chan.

ESTIMATE

Our Ref: AC2022009/OD

Vehicle number: SML2396C

Vehicle Made & Model: MAZDA 3 SP

Cost Items	Amount \$
1 Front bonnet Distorted	550.00 ✓
1 Front bonnet lock Jammed	85.00 ✓
1 Front bonnet lock bracket Distorted	45.00 ✓
1 Front bonnet lock cable Jammed	68.00 ✓
1 Front bonnet insulator Not new	110.00 X
10 Front bonnet insulator clips @ 5.50 New	55.00 X
2 Front bonnet hinges @ - L/R @ 45 Bent	90.00 ✓
1 Front bumper rubber - Inner New	36.00 ✓
1 Front bumper rubber - Outer	48.00 ✓
1 Front bumper Distorted	480.00 ✓
1 Front bumper tow cover Missing	18.00 ✓
1 Front bumper grille - CTR Deformed	115.00 ✓
1 Front bumper lower spoiler Cracked	550.00 ✓
1 Front bumper fog lamp grille New	85.00 ✓
1 Front bumper fog lamp grille base New	90.00 ✓
2 Front bumper brackets - L/R @ 65 RH Cracked	130.00 65.
2 Front bumper side retainers - L/R @ 35 New	70.00 ✓
1 Front bumper reinforcement Dented	380.00 ✓
1 Front bumper chassis frame member - RH Repair	850.00 ✓
1 Front fender - RH Distorted	260.00 ✓
1 Front fender bracket Bent	65.00 ✓
1 Front fender inner shield torn	115.00 ✓
1 Front fender wheel housing - RH Repair	455.00 X
1 Front grille Assy Cracked	485.00 200
2 Front headlamps - L/R @ 650 Cracked	1,300.00
2 Front headlamp lower brackets - L/R @ 75 RH smashed, LH ?	150.00 75
1 Front support panel Cracked	420.00 ✓
1 Air con condenser Bent	480.00 ✓
1 Air con discharge pipe New	280.00 ✓
1 Air con suction pipe New	260.00 ✓
1 Air con liquid pipe New	220.00 ✓
1 Air con compressor New	850.00 ✓
1 Air con compressor belt New	110.00 ✓
1 Air cleaner intake duct New	95.00 ✓
1 Air cleaner box New	285.00 ✓

1	TX oil cooler <i>RH new</i>	380.00 <i>X</i>
1	Power steering pump <i>new</i>	680.00 <i>X</i>
1	Power steering oil tank	85.00 <i>X</i>
1	Power steering pipe - Pump to rack <i>3 new</i>	320.00 <i>X</i>

Vehicle number: SML2396C

Vehicle Made & Model: MAZDA 3 SP

1	Power steering pipe - Oil tank <i>new</i>	65.00 <i>X</i>
1	Engine mounting - RH <i>new</i>	240.00 <i>2</i>
1	Engine mounting - LH <i>new</i>	220.00 <i>X</i>
1	Engine mounting - Rear <i>new</i>	220.00 <i>X</i>
1	Engine undercover <i>new</i>	135.00 <i>X</i>
1	Radiator assy <i>new</i>	480.00 <i>X</i>
1	Radiator auxiliary fan assy <i>new</i>	650.00 <i>400</i>
1	Radiator top hose <i>3 new</i>	45.00 <i>X</i>
1	Radiator bottom hose	45.00 <i>X</i>
1	Washer tank <i>new</i>	120.00 <i>✓</i>
1	Washer tank motor <i>new</i>	85.00 <i>X</i>
1	No. plate garnish <i>missing</i>	65.00 <i>✓</i>

Sub-total 13,520.00
~~Less 20%~~ +10% 2,704.00
 Total List 16,224.00

Special Nett Items

1 set	Front bumper clip <i>new</i>	45.00 <i>30</i>
1 set	Front fender inner shield clip <i>new</i>	45.00 <i>20</i>
1	Front no. plate <i>missing</i>	40.00 <i>✓</i>
1 bot	Air con oil <i>new</i>	60.00 <i>30</i>
1 bot	Power steering fluid <i>new</i>	60.00 <i>X</i>
1 bot	Radiator coolant <i>new</i>	60.00 <i>40</i>
1	Front tyre - RH <i>new</i>	280.00 <i>X</i>
		590.00

Labour charges

To check front electrical wiring	50.00 <i>30</i>
Towing charges	100.00 <i>60</i>
To remove, refix engine parts	200.00 <i>80</i>
To remove, refix front A/C condenser & refill A/C gas	120.00 <i>100</i>
To diagnos, erase fault memory after repair	350.00 <i>X</i>
To respray painting and etc	1,080.00 <i>800</i>
Panel beating, cut, weld remove & replacing above parts	1,200.00 <i>900</i>
Total Labour	3,100.00

Total Labour 3,100.00

total: 7478.80

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

19,914.00

total: 9499.60
1/5: 7.6K

Revised.
18/02/22. Adnan
SL/S

Excess \$3750 Adrian Ling.
SL/S
H/S OT Parts.
Not Authorised