



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL Ref: CS3/SMO22001138/Kqf3
 50 RAFFLES PLACE #03-03 Date: 07/02/2022
 SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	FBS 7795U	Veh. Inspected	SLU 1935T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2200455/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	07/02/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/01/2022	Inspection Date	08/02/2022
Survey held at	KIM AUTO 5037 ANG MO KIO INDUSTRIAL PARK 2, #01-397, ANG MO KIO INDUSTRIAL PARK 2, SINGAPORE 569540		

5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>
