



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KHONG LYNN			Ref: CS/ASM22001140/Avy3m4 Date: 13/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGX 2009D	Veh. Inspected	SMN 8118P
	Policy No.	GA588796	Coverage (\$)	0.00
	Claim No.	S2M03SOY	Excess (\$)	0.00
	Assign From	KHONG LYNN	Assign Date	07/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VELLFIRE	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	ANH208319835	Colour	BLACK
	Odometer	120855 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R20	KAPSEN	6 mm
	L/H Front Tyre	245/40 R20	KAPSEN	6 mm
	R/H Rear Tyre	245/40 R20	KAPSEN	6 mm
	L/H Rear Tyre	245/40 R20	KAPSEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/01/2022	Inspection Date	14/02/2022
	Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	