



友尼摩哆公司

UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

TPAXA

Veron

ANH208319835

DATE 14/02/2022 OUR REF UAPL1512
REPAIR ESTIMATE TO THE TOYOTA VELLFIRE NO: SMN8118P

- 1 REAR BUMPER FACE *turn*
- 1 REAR R/H BUMPER SIDE TOP GARNISH *new*
- 1 REAR R/H BUMPER SIDE WIRE GARNISH *new*
- 1 REAR R/H BUMPER SIDE RETAINER *new*

LESS 25%.....

\$ ~~1,427.40~~ 1136
\$ 201.60
\$ 67.80
\$ 92.60
\$ 1,789.40
\$ 447.35
\$ 1,342.05

1203.80

902.85

SPECIAL NETT:-

- 1 REAR BUMPER CENTRE TOP CHROME *new*
- 1 REAR BUMPER LOWER SPOILER *new*
- 1 REAR R/H SPORT WHEEL *new*

\$ 220.00
\$ 450.00
\$ 800.00

760

LABOUR CHARGES:-

- TO DISM/REWIRE DAMAGED PORTION
- TO PANEL BEAT DAMAGED PORTION & REAR FENDER
- TO PUTTY AND RESPRAY DAMAGED PORTION
- TO SPRAY UNDERCOATING IN REPAIR
- TO SEND VEHICLE FOR COMPUTER ALIGHTMENT

\$ 120.00
\$ 900.00
\$ 900.00
\$ 80.00
\$ 120.00
\$ 4,932.05

850

03 Days

total: 2512.85

L/s: 2K

Occupation:			Date of expiry:		
Chinese Name:			English Name:		
Male	Age:	Date of Birth:	Driver	Type of information:	
SINGAPORE CITIZEN			CHAY YEE EN		
NRIC NO: 20002181A			Home Office:		
ID Type: ID NO:			Contact No:		
NAME CHAY YEE EN			Address:		
Informant's Signature:			Station Day No:		
Date Time Report Made:			Vide Report No:		

REPORT OF A TRAFFIC ACCIDENT

Ref No: 25120000
10 Ubi Avenue 3 SINGAPORE 408882
Traffic Police
Police Station Of Origin

Report No: 1503101011030

