

ASS. REC. BY:

TCUM

REF:

CS/CT122081141/Btf3

Denise

## ASSIGNMENT

From:

Date:

9/2/2022

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SCA 3353X

at Workshop m/s

Bifrost Auto

of 8 Raki Bt Ave 4 Premier # 01-49

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

31,000/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRSUP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SCA 3353X

Yr Regn:

22/1/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Corolla Altis 1.6

C.C. 1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

203/83

T/Radio: Insured / Std / NI / NA

Eng/No:

12RX375735

C/No:

MR053RE41045000773

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55/16

R: 205/55/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

29/1/2022

D.O.I.

9/2/2022

Survey held at

Bifrost Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                                      |
|-------------|---|
|             | Range: 8,000/- - 9,000/-                                  |
|             | Recommended COR: LS \$ 8,350.00<br>(Red: 16,650.16 : 66%) |
|             | MV 31,000/-   |
|             | PV 21,720/-   |
|             | NV 9,280/-  |

TCUM Min  
14/3/2022

TCUM Min  
20/2/2022

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Format:

Lump Sum / L.P. : 8350



**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

**Repair Estimate**

Vehicle number: SCA3353X

Make &amp; Model: Toyota Corolla Altis

Chassis number: MR053REH104500773

| No. | Description of spare parts                 | Qty | Amount      |
|-----|--|-----|-------------|
| 1   | Bootlid 781.10                             | 1   | \$ 867.20   |
| 2   | Bootlid centre emblem                      | 1   | \$ ✓ 60.90  |
| 3   | Bootlid "Corolla" emblem                   | 1   | \$ ✓ 48.20  |
| 4   | Bootlid "Altis" emblem                     | 1   | \$ ✓ 48.80  |
| 5   | Bootlid lock                               | 1   | \$ ✓ 210.30 |
| 6   | Bootlid lock catch                         | 1   | \$ 28.70    |
| 7   | Bootlid LH lamp                            | 1   | \$ ✓ 223.70 |
| 8   | Bootlid RH lamp                            | 1   | \$ 223.70   |
| 9   | Bootlid RH hinge                           | 1   | \$ 68.90    |
| 10  | Bootlid LH hinge                           | 1   | \$ 68.90    |
| 11  | Bootlid weatherstrip                       | 1   | \$ ✓ 190.70 |
| 12  | Rear bumper                                | 1   | \$ ✓ 545.10 |
| 13  | Rear bumper LH reflector                   | 1   | \$ ✓ 40.90  |
| 14  | Rear bumper LH side retainer               | 1   | \$ ✓ 70.80  |
| 15  | Rear bumper RH side retainer               | 1   | \$ ✓ 70.80  |
| 16  | Rear bumper LH corner bracket              | 1   | \$ 60.30    |
| 17  | Rear bumper RH corner bracket              | 1   | \$ 60.30    |
| 18  | Rear bumper inner sponge                   | 1   | \$ ✓ 125.50 |
| 19  | Rear bumper reinforcement                  | 1   | \$ ✓ 398.70 |
| 20  | Rear windscreen glass rubber seal          | 1   | \$ ✓ 67.30  |
| 21  | Rear LH fender 845.10                      | 1   | \$ -986.40  |
| 22  | Rear LH fender splash shield               | 1   | \$ ✓ 59.40  |
| 23  | Rear LH fender petrol cover 85.00          | 1   | \$ 103.60   |
| 24  | Rear LH fender petrol cover lock 85.00     | 1   | \$ 94.50    |
| 25  | Rear LH fender petrol filler neck          | 1   | \$ 252.40   |
| 26  | Rear LH fender petrol cover rivets         | 2   | \$ ✓ 19.00  |
| 27  | Rear LH fender inner lower air vent 125.00 | 1   | \$ 140.90   |
| 28  | Rear LH fender inner trim board            | 1   | \$ ✓ 335.50 |
| 29  | Rear LH fender inner wheel housing 189.90  | 1   | \$ 299.00   |
| 30  | Rear LH fender inner panel 225.80          | 1   | \$ 487.00   |
| 31  | Rear LH sub chassis frame                  | 1   | \$ 2468.00  |
| 32  | RH taillamp                                | 1   | \$ 395.40   |
| 33  | RH taillamp sponge gasket                  | 1   | \$ 28.40    |
| 34  | RH taillamp panel                          | 1   | \$ 374.45   |
| 35  | RH taillamp lower bracket                  | 1   | \$ 59.30    |

2014

DDV  
NECV  
JMV  
NDX  
BRV  
NDX  
NDX  
TN  
BRV  
NECV  
NSX  
BTU  
NECV  
DDV  
TN  
DDV  
BRV  
NDX  
NECV  
BRV  
BRV  
DDV  
DDV  
NDX  
NDX  
NDX



2015

|    |   |        |              |                        |
|----|---|--------|--------------|------------------------|
| 36 | End panel                               |        | 1            | \$ ✓ 595.80            |
| 37 | End panel inner garnish                 |        | 1            | \$ ✓ 210.30            |
| 38 | Spare tyre LH side panel                |        | 1            | \$ <del>145.00</del>   |
| 39 | Spare tyre top cover                    |        | 1            | \$ 485.10              |
| 40 | LH rear door                            |        | 1            | \$ ✓ 1,079.40          |
| 41 | LH rear door frame black tape           | 40.00  | 1            | \$ 73.00               |
| 42 | LH rear door outer chrome moulding      | 109.50 | 1            | \$ 144.50              |
| 43 | LH rear door outer handle               |        | 1            | \$ <del>155.00</del>   |
| 44 | LH rear door outer handle side cover    |        | 1            | \$ <del>52.00</del>    |
| 45 | LH rear door outer handle inner bracket |        | 1            | \$ <del>155.60</del>   |
| 46 | LH rear door inner trim board           | 672.00 | 1            | \$ 940.30              |
| 47 | LH rear door glass regulator gear       |        | 1            | \$ <del>265.70</del>   |
| 48 | LH rear door glass regulator gear motor |        | 1            | \$ <del>585.00</del>   |
| 49 | LH rear door weatherstrip               |        | 1            | \$ ✓ 178.40            |
| 50 | LH rear door lock                       |        | 1            | \$ ✓ 371.20            |
| 51 | Rear LH sport rim                       | 450.00 | 1            | \$ 1,044.10            |
| 52 | Rear axle beam                          |        | 1            | \$ <del>3,440.00</del> |
| 53 | Rear LH wheel bearing                   | 562.00 | 1            | \$ <del>967.00</del>   |
| 54 | Rear LH shock absorber                  | 150.00 | 1            | \$ <del>231.10</del>   |
| 55 | LH front door                           |        | 1            | \$ <del>1,102.30</del> |
| 56 | LH front door frame black tape          | 40.00  | 1            | \$ 45.60               |
| 57 | LH front door outer chrome moulding     |        | 1            | \$ <del>133.00</del>   |
| 58 | LH front door lock                      |        | 1            | \$ <del>371.20</del>   |
|    |   |        |              |                        |
|    |   |        |              |                        |
|    |   |        |              |                        |
|    |   |        |              |                        |
|    |   |        | Total        | \$ 22,353.55           |
|    |   |        | Less 25%     | \$ 5,588.39            |
|    |   |        | <b>Total</b> | <b>\$ 16,765.16</b>    |

DDV ✓  
BRV ✓  
NDX  
NSX  
BT ✓  
NEC ✓  
NEC ✓  
NDX  
NDX  
NDX  
BRV ✓  
} NDX  
TN ✓  
JMV  
CUT ✓  
NDX  
JMV ✓  
BT ✓  
CUT X R  
NEC ✓  
} NN X

| No. | Special Nett Items                               |      | Amount    |
|-----|--|------|-----------|
| 1   | Bootlid inner trim clips                         | 1set | \$ 70.00  |
| 2   | Bootlid chrome moulding clips                    | 1set | \$ 40.00  |
| 3   | Rear bumper clips                                | 1set | \$ 70.00  |
| 4   | End panel inner garnish clips                    | 1set | \$ 50.00  |
| 5   | End panel joint sealant                          | 1    | \$ 70.00  |
| 6   | Rear windscreen glass sealant                    | 1    | \$ 70.00  |
| 7   | Rear windscreen glass inner seal                 | 1    | \$ 50.00  |
| 8   | Rear LH fender joint sealant                     | 1    | \$ 70.00  |
| 9   | Rear LH fender inner wheel housing joint sealant | 1    | \$ 50.00  |
| 10  | Rear LH fender inner panel joint sealant         | 1    | \$ 50.00  |
| 11  | Rear LH fender inner trim clips                  | 1set | \$ 70.00  |
| 12  | LH taillamp lock clips                           | 1set | \$ 45.00  |
| 13  | Spare tyre LH side panel joint sealant           | 1    | \$ 40.00  |
| 14  | LH rear door inner trim board clips              | 1set | \$ 70.00  |
| 15  | LH front door inner trim board clips             | 1set | \$ 70.00  |
| 16  | LH rear tyre                                     | 1    | \$ 320.00 |
| 20  | Rear bumper reverse sensor                       | 1set | \$ 280.00 |
|     |  |      |           |
|     |  |      |           |

NSX  
NEC ✓  
NEC ✓  
NEC ✓  
NEC ✓  
NAX  
NDX  
SCV ✓



|    | Labour and painting  |         | Amount        |
|----|--|---------|---------------|
| 1  | Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas | 1200.00 | \$ 2,400.00 ✓ |
| 2  | Spray painting on affected areas and panels  | 1200.00 | \$ 1,800.00 ✓ |
| 3  | Check wiring and lighting system   | 50.00   | \$ 120.00 ✓   |
| 4  | Apply rust coating chemical on affected areas and panels   |         | \$ 180.00 NNX |
| 5  | Remove and reinstall rear windscreen glass to assist repair  | 120.00  | \$ 220.00 ✓   |
| 6  | Remove and replace bootlid inner mechanism to new bootlid  | 70.00   | \$ 100.00 ✓   |
| 7  | Remove and reinstall bootlid reverse camera to assist repair   |         | \$ 100.00 NNX |
| 8  | Remove and replace rear bumper reverse sensors   | 60.00   | \$ 100.00 ✓   |
| 9  | Remove and replace rear inner trim, garnish and boards to assist repair  | 80.00   | \$ 240.00 ✓   |
| 10 | Remove, reinstall and replace fuel tank, pipes, sensor and cover to assist repair  | 80.00   | \$ 150.00 ✓   |
| 11 | Remove and replace rear undercarriage parts to assist repair   |         | \$ 450.00 NNX |
| 12 | Test drive and adjust wheel alignment system   |         | \$ 100.00 NNX |
| 13 | Remove and replace LH rear door inner mechanism to new door  | 80.00   | \$ 120.00 ✓   |
| 14 | Remove and replace LH front door inner mechanism to new door   |         | \$ 120.00 NNX |
| 15 | Remove and reinstall roof lining, seats, carpet and seat belts to assist repair  |         | \$ 550.00 NNX |
|    |  | 2940.00 |               |

Total Amount:

\$ 25,000.16

Survey  
11/2/2022

Resurvey  
15/2/2022

143 hrs

1345 hrs

TGrimm

TGrimm

Lump sum repair  
Repair days 8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LS 8,350.12

TGrimm  
14/3/2022

Parts 6983.93

SN 530.00

Labour 2940.00

10,453.93

@20% 2,090.79

8363.14

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                               |
|-------------------------------|-------------------------------|
| Owner ID Type:                | Singapore NRIC                |
| Owner ID:                     | 360Z                          |
| Vehicle Details               |                               |
| Vehicle No.:                  | SCA3353X                      |
| Vehicle to be Exported:       | Yes                           |
| Intended Deregistration Date: | 07 Feb 2022                   |
| Vehicle Make:                 | TOYOTA                        |
| Vehicle Model:                | TOYOTA COROLLA ALTIS 1.6L CVT |
| Primary Colour:               | Silver                        |
| Manufacturing Year:           | 2013                          |
| Engine No.:                   | 1ZR375735                     |
| Chassis No.:                  | MR053REH104500773             |
| Maximum Power Output:         | 90.0 kW (120 bhp)             |
| Open Market Value:            | \$18,777.00                   |
| Original Registration Date:   | 22 Jan 2014                   |
| First Registration Date:      | 22 Jan 2014                   |
| Transfer Count:               | 1                             |
| Actual ARF Paid:              | \$13,777.00                   |
| Intended PARF Rebate Details  |                               |
| PARF Eligibility:             | Yes                           |
| PARF Eligibility Expiry Date: | 21 Jan 2024                   |
| PARF Rebate Amount:           | \$7,577.00                    |
| Intended COE Rebate Details   |                               |
| COE Expiry Date:              | 21 Jan 2024                   |
| COE Category:                 | A - Car (1600cc & below)      |
| COE Period(Years):            | 10                            |
| QP Paid:                      | \$72,369.00                   |
| COE Rebate Amount:            | \$14,143.00                   |
| <b>Total Rebate Amount:</b>   | <b>\$21,720.00</b>            |

The information contained herein is correct as at 07 Feb 2022

OK

MV 31,000/2  
PV >1,720/2  
NV 9,280/2

Tan Min

13/3/2022



Date of Accident : 29/1/2022 Accident Time: 1900 (24-HR-FORMAT)  
Accident Place : TPE Towards SLE before Selatg Link Exit  
Vehicle Reg. No (Car plate No.) : SCA3353 X Vehicle Make/Model: TOYOTA ALTI  
Insurance Company : NTUC Policy No. 5106936122-03  
Name of Registered Owner : Company / Individual Boh Sioh Kee  
ID of Registered Owner : Co Reg No: \_\_\_\_\_ Owner's NRIC No: S9321447A  
: Co Contact No: \_\_\_\_\_ Owner's Contact No: 97492862  
DRIVER'S Name : Eng Qing Hua DRIVER'S NRIC No: S9321447A  
DRIVER'S Date of Birth : 04/06/1943 DRIVER'S License Pass Date 19/1/2015  
Relationship bet. Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: \_\_\_\_\_  
DRIVER'S Address : 117 Bukit Merah Central #11-3751  
DRIVER'S Contact No./ Alt No. : 1) 9169 1305 2) \_\_\_\_\_  
DRIVER'S Occupation : INDOOR \ OUTDOOR (eg. working inside or outside of an ofc)  
Email Address : engqinghwa@gmail.com  
Weather & Road Surface : CLEAR \ DRY \ RAINING & WET \ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
Number of Passengers (including Driver): 2 Name & Gender: Mureen (F)  
Was the accident reported to the police? YES \ NO  
Was there any video Captured by car camera: YES \ NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
Any injuries, if yes (name of the injured person) Eng Qing Hua, Mureen  
**Other Party Driver's Particulars (if any)**  
Vehicle Reg No: 6BJ8878E Vehicle Reg No: \_\_\_\_\_  
Vehicle Make/Model: \_\_\_\_\_ Vehicle Make/Model: \_\_\_\_\_  
Name DRIVER: \_\_\_\_\_ Name DRIVER: \_\_\_\_\_  
IC No. DRIVER: \_\_\_\_\_ IC No. DRIVER: \_\_\_\_\_  
DRIVER'S Contact & add: \_\_\_\_\_ DRIVER'S Contact & add: \_\_\_\_\_



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### **Sketch Plan**





refer to police report  
T/20220130/2061

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel





**SINGAPORE  
POLICE FORCE**



T/20220130/2061

Police Station Of Origin:  
Bukit Merah West N.P.C  
500 Bukit Merah View #01-01 SINGAPORE  
159682  
Tel No: 1800-3779999

1 of 4

Report No. T/20220130/2061

**REPORT OF A TRAFFIC ACCIDENT**

|  |                  |                          |
|--|------------------|--------------------------|
| Date/Time Report Made:<br>30/01/2022 18:33 | Vide Report No.: | Station Diary No.:<br>22 |
|--|------------------|--------------------------|

|  |            |  |                              |
|--|------------|--|------------------------------|
| <b>Informant's Particulars</b>           |            |  |                              |
| Name of Informant:<br>ENG QING HUA       |            | Address:<br>APT BLK 117 BUKIT MERAH CENTRAL #11-3751<br>SINGAPORE 150117 |                              |
| ID Type / ID No.:<br>NRIC NO / S9321447A |            | Contact No.:<br>Home/Office: Mobile: 91691305                            |                              |
| Nationality:<br>SINGAPORE CITIZEN        |            | Email:   |                              |
| Sex:<br>Male                             | Age:<br>28 | Date of Birth:<br>04/06/1993   | Type of Informant:<br>Driver |
| Race:<br>Chinese                         |            | Language:<br>English   | Institution / School Name:   |
| Occupation:<br>ENTREPRENEUR              |            | Driving Licence Information:<br>Class: 3 Date of Expiry:                 |                              |

|  |                  |                                    |  |                                     |
|--|------------------|------------------------------------|--|-------------------------------------|
| <b>General Information of the Accident</b>                   |                  |                                    |  |                                     |
| Type of Accident:  | Injury<br>Others | Drink<br>Drive:<br>No              | Date/Time of Accident:<br>29/01/2022 19:00 | Type of Location:<br>Straight Road  |
| Location:<br><br>TAMPINES EXPRESSWAY                         |                  |                                    |  |                                     |
| Weather:<br>Clear  |                  | Road Surface:<br>Dry               | Road Speed Limit:<br>90 Km/h               |                                     |
| Traffic Flow:<br>Dual Carriage Way                           |                  | Traffic Control:<br>Not Controlled | Traffic Volume:<br>Moderate                |                                     |
| Type of Collision:<br>Between Moving Vehicles - Head To Rear |                  |                                    |  | Anyone conveyed by ambulance:<br>No |

| Details of Vehicle Involved |       |        |       |        |                   |                 |
|-----------------------------|-------|--------|-------|--------|-------------------|-----------------|
| Vehicle No.                 | Type  | Make   | Model | Color  | Condition         | No of Passenger |
| GBJ8878E                    | Lorry | TOYOTA | Dyna  | Silver | Slightly Damaged  | 1               |
| SCA3353X                    | Car   | TOYOTA | Altis | Silver | Seriously Damaged | 1               |

|                                   |                                |
|-----------------------------------|--------------------------------|
| <b>Details of Person Involved</b> |                                |
| Any Pedestrian Involved: No       |                                |
| No. of Pedestrians Injured: NIL   | Use of Pedestrian Crossing: NA |





**SINGAPORE  
POLICE FORCE**



T/20220130/2061

Police Station Of Origin:  
Bukit Merah West N.P.C  
500 Bukit Merah View #01-01 SINGAPORE  
159682  
Tel No: 1800-3779999

2 of 4

Report No. T/20220130/2061

**CONTINUATION OF REPORT**

|                                   |   |  |                                   |
|-----------------------------------|---|--|-----------------------------------|
| <b>Driver</b>                     |   |  |                                   |
| Name                              | LI GANG   | ID No.                                 | G6396363T                         |
| Related Vehicle                   | GBJ8878E (Lorry)                                  | Contact No.                            | 83231168                          |
| Hospital/Clinic                   | NIL   | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL   | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL   | Degree of Injury                       | NIL                               |
| <b>Driver</b>                     |   |  |                                   |
| Name                              | ENG QING HUA                                      | ID No.                                 | S9321447A                         |
| Related Vehicle                   | SCA3353X (Car)                                    | Contact No.                            | 91691305                          |
| Hospital/Clinic                   | KAO & TAN FAMILY MEDICAL CENTRE & SURGERY PTE LTD | Class of Driving Licence & Expiry Date | Class: 3<br>Date of Expiry: NIL   |
| Date Treatment                    | 30/01/2022  | Date Discharge                         | 30/01/2022                        |
| No. of Days granted Medical Leave | 04  | Degree of Injury                       | Slight                            |
| <b>Passenger</b>                  |   |  |                                   |
| Name                              | MAREEN LIANG MA REEN                              | ID No.                                 | S9590865I                         |
| Related Vehicle                   | SCA3353X (Car)                                    | Contact No.                            | 83059455                          |
| Hospital/Clinic                   | KAO & TAN FAMILY MEDICAL CENTRE & SURGERY PTE LTD | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | 30/01/2022  | Date Discharge                         | 30/01/2022                        |
| No. of Days granted Medical Leave | 04  | Degree of Injury                       | Slight                            |

**Brief Details.**

On 29/01/2022 at about 1900hrs, I was driving my car along TPE with my girlfriend who was sitting on the front passenger seat. I was driving along lane 3 before exit to Seletar Link when the vehicles in front suddenly stopped. I was driving at about 70km/h when I performed an emergency brake when me and my girlfriend felt a huge collision from the back of the car. I then move to the side and came out to check on the vehicle. There was another lorry who was at the rear left side to my vehicle when it collided to my car causing serious damage to the rear left side of my car. The lorry driver also came out and apologized to us after the accident. I also saw his lorry skidding and hitting the side railing as it stopped. We exchanged particulars and I called my insurance company who called the tow truck down and tow my car away. During that point of time, no one was injured and there were no police or ambulance that came to the scene. On 30/01/2022, my girlfriend felt pain on the back of her neck while I felt pain on the left side of my shoulder so we went to see a doctor. The doctor told us that it was caused by the whiplash and gave us





**SINGAPORE  
POLICE FORCE**



T/20220130/2061

3 of 4

Police Station Of Origin:  
Bukit Merah West N.P.C  
500 Bukit Merah View #01-01 SINGAPORE  
159682  
Tel No: 1800-3779999

Report No. T/20220130/2061

**CONTINUATION OF REPORT**

days of MC. The company of the lorry driver is from CMJ Engineering Pte Ltd.