

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0079/2022/JT
DATE : 4-Feb-22
WIP : 10128

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ENG KWANG CHIANG
ADDRESS : 52B HASSAN DRIVE
SINGAPORE 757135
TELEPHONE : HP +65 97929678
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900157269-01
VEHICLE NO : SMZ 3280 Y
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 8/3/2021
ENGINE NO : CHZ C34586
CHASSIS NO : WAUZZZ8V5LA007331
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Feb-22
PLACE OF ACCIDENT : WOODLANDS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 3280 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 500	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL AND FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACCUM AND REGAS.	S/N \$ 1,400.00 /	
4	TO RENEW FRONT WINDSCREEN.	S/N \$ 480.00 /	
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$ 400.00 ?	
SUB TOTAL LABOUR CHARGES (See agent)		: \$ <u>3,340.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 3280 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$ 200.00	150
7	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	3000
8	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH UPPER A-PILLARS.	\$ 5,500.00	2300
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 15,024.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 3280 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / <i>DD</i>	1	\$ 1,987.00	
2	FRONT BUMPER FIXING PARTS X	1	\$ 195.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH ?	2	\$ 86.00	
4	FRONT BUMPER GRILLE - CENTER ?	1	\$ 179.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER ?	1	\$ 571.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH ?	2	\$ 636.00	
7	FRONT BUMPER TRIM COVER - LH / RH ?	2	\$ 364.00	
8	FRONT BUMPER ADAPTER - LH / RH -	2	\$ 84.00	
9	RADIATOR GRILLE / <i>BR</i>	1	\$ 1,406.00	
10	RADIATOR GRILLE CLOSING ELEMENT ?	1	\$ 210.00	
11	AIR COND STICKER / <i>MC</i>	1	\$ 9.00	
12	CAUTION STICKER / <i>MC</i>	1	\$ 16.00	
13	FRONT BUMPER AIR GUIDE GRILLE - LH / RH ?	2	\$ 420.00	
14	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 847.00	
15	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 211.00	
16	FRONT BUMPER REINFORCEMENT BEAM COVER ?	1	\$ 136.00	
17	HORN - LH / RH ?	2	\$ 426.00	
18	FRONT FENDER (LH / RH) / <i>DD</i>	12	\$ 1,908.00	
19	POP RIVET / <i>MC</i>	10	\$ 38.00	
20	FRONT FENDER ATTACHMENT PARTS X	1	\$ 75.00	
SUB TOTAL SPARE PARTS		:	\$ 9,804.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 3280 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET (LH) RH BT	21	\$	92.00
22	FRONT FENDER BRACE - LH / RH ?	2	\$	214.00
23	FRONT FENDER END BRACKET - LH / RH ?	2	\$	62.00
24	FRONT WHEEL HOUSING LINER - LH / RH X	2	\$	366.00
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS X	1	\$	93.00
26	BONNET / ON	1	\$	3,134.00
27	BONNET ATTACHMENT PARTS X	1	\$	172.00
28	BONNET HINGE - LH / RH BT	2	\$	136.00
29	BONNET EDGE PROTECTION - MC	1	\$	31.00
30	BONNET STRIKER - LH (RH) BT	21	\$	246.00
31	BONNET CATCH HOOK - UPPER ?	1	\$	100.00
32	BONNET MICRO-SWITCH (LH) BT	21	\$	455.00
33	BONNET CATCH HOOK - LOWER ?	1	\$	71.00
34	BONNET BOWDEN CABLE - CENTER ?	1	\$	64.00
35	BONNET BOWDEN CABLE COVER CAP ?	1	\$	11.00
36	FRONT FENDER INNER COVER - LH / RH ?	2	\$	92.00
37	PLENUM CHAMBER (2nd M grille) - MC	1	\$	199.00
38	GAS FILLED STRUT X	1	\$	110.00
39	HEADLIGHT - LH / RH BR	(2)	\$	10,910.00
40	HEADLIGHT POWER MODULE - LH ?	1	\$	850.00
SUB TOTAL SPARE PARTS		:	\$	17,408.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 3280 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT HEAT SINK - LH ?	1	\$ 818.00	
42	HEADLIGHT CONTROL UNIT ?	1	\$ 625.00	
43	HEADLIGHT HOSE - LH ?	1	\$ 46.00	
44	LIFT CYLINDER - LH / RH ?	2	\$ 312.00	
45	LIFT CYLINDER HOSE ?	1	\$ 78.00	
46	WASH WATER RESERVOIR ?	1	\$ 225.00	
47	LOCK CARRIER / BR	1	\$ 806.00	
48	A/C CONDENSER ?	1	\$ 569.00	
49	REFRIGERANT LINE ?	1	\$ 499.00	
50	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 21.00	
51	ADDITIONAL RADIATOR ?	1	\$ 959.00	
52	RADIATOR ?	1	\$ 1,061.00	
53	RADIATOR COOLANT ?	6	\$ 282.00	
54	RADIATOR FAN RING ?	1	\$ 1,464.00	
55	RADIATOR AIR GUIDE - LH / RH ?	2	\$ 56.00	
56	RADIATOR SEAL - RH OUTER ?	1	\$ 9.00	
57	RADIATOR AIR GUIDE - UPPER CENTER ?	1	\$ 14.00	
58	AIR INTAKE - LOWER COVER ?	1	\$ 59.00	
59	AIR INTAKE - UPPER COVER ?	1	\$ 30.00	
60	AIR INTAKE HOSE ?	1	\$ 69.00	
SUB TOTAL SPARE PARTS		:	\$ 8,002.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 3280 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	AIR INTAKE AIR GUIDE ?	1	\$	21.00
62	FRONT WINDSCREEN - BR	1	\$	1,072.00
63	FRONT RAIN SENSOR GEL FOIL - NH	1	\$	130.00
64	SPRING CLIP X	1	\$	23.00
65	PRIMER - NH	1	\$	22.00
66	WINDSCREEN WATER DEFLECTOR STRIP - LH / RH X	2	\$	208.00
67	FRONT NO PLATE - BT	S/N	\$	60.00
68	FRONT WINDSCREEN SEALANT - NH	S/N	\$	200.00
69	SUNDRIES ?		\$	400.00
TOTAL SPARE PARTS		:	\$	37,350.00
TOTAL LABOUR CHARGES		:	\$	15,024.00
GRAND TOTAL		:	\$	52,374.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
7/2/12, 12.30p

on-hill
Excess
1/2 d/s
P/P
by Ben

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT