



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22001161/Eqf3e2	
			Date: 24/03/2022	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SG 6283Z	Veh. Inspected	SCY 5926D
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000337MFBP	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	08/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	B.M.W. 320I	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WBA3B16060NS51576	Colour	BLACK
	Odometer	171994 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	MICHELIN	4 mm
	L/H Front Tyre	205/55 R16	MICHELIN	4 mm
	R/H Rear Tyre	205/55 R16	MICHELIN	4 mm
	L/H Rear Tyre	205/55 R16	MICHELIN	4 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	03/02/2022	Inspection Date	07/03/2022
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
<b>5a. Remarks</b>				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	