

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 60807**  
Date Estimated : **04/02/2022**  
Prepared By : **Foong Shiuh Jye**

**- ESTIMATE REPAIR FOR -**  
**Chua Kuan Seah (Cai GuangCheng)**  
**118 Edgefield Plains**  
**#15-302**

**Singapore 820118**

**- ACCOUNT - 303**  
**MS First Capital Insurance Limited**  
**6 Raffles Quay**  
**#21-00**  
**Singapore 048580**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SCY5926D</b>	<b>WBA3B16060NS51576</b>	<b>28/02/2014</b>	<b>320iA/4</b>	<b>74898</b>

DESCRIPTION	ORIGINAL PRICE	NETT
To replace front left fender and attachments including make good the front bumper and knock out dented area caused by the accident.	1,275.00	1,275.00
To respray front bumper and front left fender.	1,826.00	1,826.00
To carry out body cavity preservation. (Per panel).	112.00	112.00
To remove old PDC assembly and reconnect to new bumper including conduct check for proper function.	168.00	168.00
To check electrical wiring system at the front section for proper function.	168.00	168.00
Sundries.	80.00	80.00

DESCRIPTION	UNIT PRICE	QTY	NETT
FRT LH SIDE PANEL	706.15	1.00	706.15
FRT LH BOTTOM MOUNTING SIDE PANEL	13.25	1.00	13.25
PLAQUE 82MM	72.85	1.00	72.85

### # SUPPLEMENTARY ITEMS

Total Labour :	3,629.00
Total Parts :	792.25
Total Labour & Parts :	4,421.25
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,421.25
GST @7%:	309.49
Grand Total :	4,730.74