



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KHONG LYNN			Ref: CS/ASM22001163/Rqy3e2 Date: 10/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBS 1371Z	Veh. Inspected	SMX 3435D
	Policy No.		Coverage (\$)	0.00
	Claim No.	S2M03SS1	Excess (\$)	0.00
	Assign From	KHONG LYNN	Assign Date	08/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT HYBRID 1.5 A	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	GP53416468	Colour	RED
	Odometer	82024 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	FIRENZA	6 mm
	L/H Front Tyre	185/60 R15	FIRENZA	6 mm
	R/H Rear Tyre	185/60 R15	FIRENZA	6 mm
	L/H Rear Tyre	185/60 R15	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/01/2022	Inspection Date	21/02/2022
	Survey held at	HENG YAP SENG AUTO SERVICE 160 SIN MING DRIVE #08-13 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	