

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 07 Apr 2022

Preliminary Advice

Insured Vehicle No	: SLH4025T		
TP Vehicle No	: SML3684P	Accident Date	: 28/01/2022
Make	: SUZUKI SWIFT	Assignment Date	: 07/02/2022
Date of Inspection	: 08/02/2022	Est. Duration of Repair	: 14
Inspection At	: AT AUTO CONSULTANT (HQ) NO 19 DEFU LANE 8 DEFU INDUSTRIAL ESTATE SINGAPORE 539320		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,554.15
Revised Amount	:S\$	17,923.13
Check Items (Estimated)	:S\$	0.00
Total	:S\$	17,923.13
Lump Sum Repair	:S\$	12,600.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	22,000.00
COE / PARF Rebate	:S\$	9,128.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,872.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (x) Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.