

AT AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 29.01.2022
Vehicle No: GBD7963E
Owner: DATA TERMINATOR PTE LTD
Date of Accident: 25.01.2022
Make & Model: MERCEDES BENZ CITAN 109 CDI
Chassis No : WDF4156052U149903

ESTIMATE FOR ACCIDENT VEHICLE NO GBD7963E

PARTS

- | | | |
|---|----------------------------|------|
| 1 | 1 Rear bumper | 1070 |
| 2 | 1 Rear bumper reflector RH | |
| 3 | 1 Rear bumper lid RH | |
| 4 | 1 Rear bumper retainer RH | |
| 5 | 1 Tail lamp RH | |
| 6 | 1 Tail lamp top panel RH | 2160 |
| 7 | 1 Rear fender | |

SUB TOTAL
LESS 10%
DISCOUNTED SUB TOTAL

Bumper \$1,070.00 ✓
CMT \$132.00 ✓
mgcm \$243.00 ✓
su \$189.00 X
br \$235.00 ✓
r \$154.00 X
B1 \$2,160.00 X
\$4,183.00
\$418.30
\$3,764.70

S. NETT ITEM

SUB TOTAL
LESS 0 %
DISCOUNTED SUB TOTAL

\$0.00
\$0.00
\$0.00

LABOUR

- | | |
|---|---|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spray painting on affected area |
| 3 | Apply putty and anti-corrosion to affected parts |
| 4 | Remove/refix reverse sensor |

SUB TOTAL (LABOUR)

\$1,500.00 700
\$1,000.00 450
\$150.00 30
\$80.00 50
\$2,730.00

SUB TOTAL (PARTS)

\$3,764.70

S.NET ITEM

\$0.00

SUB TOTAL (LABOUR)

\$2,730.00

ESTIMATED GRAND TOTAL

\$6,494.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 2

Acknowledged by Repairer

Signature:

Date: