



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22001167/Ktf3e2	
			Date: 25/02/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 7018D		Veh. Inspected	SLH 23A
Policy No.			Coverage (\$)	0.00
Claim No.	D22000354MFCV		Excess (\$)	0.00
Assign From	RACHELWU LIMEI		Assign Date	08/02/2022
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA180		c.c	1595
Engine No.	HIDDEN		Year of Reg.	2014
Chassis No.	WDD1173422N137831		Colour	METALLIC SILVER
Odometer	110811 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		225/40 R18	CONTINENTAL	7 mm
L/H Front Tyre		225/40 R18	CONTINENTAL	7 mm
R/H Rear Tyre		225/40 R18	CONTINENTAL	7 mm
L/H Rear Tyre		225/40 R18	CONTINENTAL	7 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/02/2022		Inspection Date	10/02/2022
Survey held at	TENG MENG MOTOR SERVICE 176 SIN MING DRIVE SIN MING AUTOCARE #04-01 & #04-10 SINGAPORE 575721			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	