

LKK Auto Consultants Pte Ltd

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 5918T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	895.05	895.05
2	REAR BUMPER SIDE HOLDER @\$67.50	O/S NECESSARY	135.00	67.50
1	REAR RH MUD FLAP	CUT	155.00	155.00
1	REAR RH FENDER	DENTED	1,845.00	1,845.00
1	REAR RH FENDER INNER TRIM	NOT NECESSARY	255.00	-
1	REAR RH QUARTER GLASS	NOT NECESSARY	285.00	-
	LESS 10% DISCOUNT		-	-296.26
			3,570.05	2,666.29
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	380.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR RH SPORT RIM (SN)	CUT	1,317.00	850.00
1	REAR RH TYRE (SN)	NOT NECESSARY	550.00	-
1	REAR RH QUARTER GLASS SEALANT (SN)	NECESSARY	120.00	60.00
			2,427.00	940.00
	<u>LABOUR</u>			
	TO SUPPLY REAR RH QUARTER GLASS SEALANT.		50.00	40.00
	REMOVE & REINSTALL QUARTER GLASS.		100.00	60.00
	TO CHECK WHEEL ALIGNMENT.		100.00	80.00
	REMOVE & REINSTALL REVERSE SENSOR.		200.00	50.00
	REMOVE & REINSTALL BOOTLID INNER GARNISH.	NOT NECESSARY	200.00	-
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		1,600.00	700.00
	RESPRAY PAINTING.		1,300.00	500.00
	TUFF KOTE.		100.00	60.00
	TO DISENGAGE HIGH VOLTAGE CABLE.		200.00	150.00
			3,850.00	1,640.00
	GRAND TOTAL		9,847.05	5,246.29

Report Ref No. CS/SMO22001168/Avf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMO22001168/Avf3e2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.