



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22001168/Avf3e2	
			Date: 28/06/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 3207B	Veh. Inspected	SNB 5918T
	Policy No.	D21MTPCVE002759	Coverage (\$)	0.00
	Claim No.	CMTD2200380/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	08/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TESLA MODEL 3	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	LRW3F7EL9MC263502	Colour	BLUE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/35 R20	PIRELLI	6 mm
	L/H Front Tyre	235/35 R20	PIRELLI	6 mm
	R/H Rear Tyre	235/35 R20	PIRELLI	6 mm
	L/H Rear Tyre	235/35 R20	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/01/2022	Inspection Date	14/02/2022
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	