



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
SOMPO INSURANCE SINGAPORE PL			Ref: CS/SMO22001168/f3		
50 RAFFLES PLACE #03-03			Date: 08/02/2022		
SINGAPORE LAND TOWERSINGAPORE 048623			Code: SMO		
1. Policy Particulars :- THIRD PARTY CLAIM					
Insured Veh.		GBE 3207B	Veh. Inspected SNB 5918T		
Policy No.			Coverage (\$)		0.00
Claim No.		CMTD2200380/SYH	Excess (\$)		0.00
Assign From		GRACE TEO	Assign Date		08/02/2022
2. Vehicle Particulars & Condition					
Make & Model			c.c		0
Engine No.		HIDDEN	Year of Reg.		
Chassis No.			Colour		
Odometer		-	Steering		
Brakes			Modification		
General					
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
5. General Information					
	Accident Date	26/01/2022	Inspection Date		08/02/2022
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP			
		1 KAKI BUKIT AVE 6			
		#01-61 AUTOBAY			
		SINGAPORE 417883			
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				