

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

LRW 3F 7EL SMC 263502

Name : TAN TAM PIN

Vehicle No : SNB 5918 T

TP Somp
vecon

Make/Model : TESLA DUAL MODEL 3

Accident date : 26.01.2022

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear bumper <i>Deformed</i>	1	\$ 895.05 ✓
2	Rear bumper side holder @ \$67.50 <i>RH New</i>	2	\$ 135.00 <i>67.50</i>
3	Rear RH mud flap <i>Cut</i>	1	\$ 155.00 ✓
4	Rear RH fender <i>Dented</i>	1	\$ 1,845.00 ✓
5	Rear RH fender inner trim <i>New</i>	1	\$ 255.00 X
6	Rear RH quarter glass <i>New</i>	1	\$ 285.00 X
		Total	\$ 3,570.05

Special Nett Items

1	Rear bumper reverse sensor (1 set) <i>New</i>	1	\$ 380.00 X
2	Rear bumper clips (1 set) <i>New</i>	1	\$ 10.00 <i>30</i>
3	Rear RH sport rim <i>Cut</i>	1	\$ 1,317.00 <i>850</i>
4	Rear RH tyre <i>New</i>	1	\$ 550.00 X
5	Rear RH quarter glass sealant <i>NEC</i>	1	\$ 2,307.00
		Total	\$ 2,307.00

Labour Cost

1 To supply rear RH quarter glass sealant	\$ 50.00	40
2 Remove & reinstall quarter glass	\$ 100.00	60
3 To check wheel alignment	\$ 100.00	80
4 Remove & reinstall reverse sensor	\$ 200.00	50
5 Remove & reinstall bootlid inner garnish	\$ 200.00	X
6 Remove ,replace & repair consistent to the accident	\$ 1,600.00	700
7 Respray painting	\$ 1,300.00	500
8 Tuff kote	\$ 100.00	60
1640 Total	\$ 3,650.00	

9 To disengage high voltage cable

Grand Total

\$ 9,527.05

9847.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5246.29

L/S A 2K

050up

42K