

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22001171/Bqf3s2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date:	20/04/2022	
			Code	: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJQ 405H	Veh. Inspected	SMG 177H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10013741/CD	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	08/02/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN TOURAN 1.4	C.C	1395	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	WVGZZZ1TZKW003474	Colour	GREY	
	Odometer	42643 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/ 55R17	MICHELIN	6 mm	
	L/H Front Tyre	215/ 55R17	MICHELIN	6 mm	
	R/H Rear Tyre	215/ 55R17	MICHELIN	6 mm	
	L/H Rear Tyre	215/ 55R17	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DANAGES SEE DETAILS.				
5.	General Information				
	Accident Date	05/02/2022	Inspection Date	10/02/2022	
	Survey held at BIFROST AUTO PTE LTD				
		8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: