



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 32199

Your Reference : DHOM110178172100
Accident Date : 26-Jan-2022

Date : 07-Feb-2022

Our Ref : 021617 / MH

PAGE : 1

WONG YOKE EU (MDM)
C/O UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD
#28-01
SPRINGLEAF TOWER
Singapore 079909

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6L (2014) SKQ3950T

1 pc front bumper	190.00 c	
1 pc LH front bumper side retainer	35.00 c	
1 pc LH front bumper foglamp	135.00 c	
1 pc LH front bumper foglamp cover	55.00 c	
10 pcs front bumper clips	@ S\$ 1.50	15.00 c
1 pc LH headlamp assy	650.00 c	

	1,080.00	
Add 10% :	108.00	

		1,188.00

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts. 400.00

To focus headlamps. To check front
wiring and lighting operation. 50.00

To putty and respray on affected
portions. 450.00

To conduct front wheel alignment
test. 100.00

Total : S\$ 2,188.00

Singapore Dollars Two Thousand One Hundred and
Eighty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.