

ESTIMATED REPAIR COST DETAILS

ACC22020001

To: MSIG AISIA PTE LTD
4 SHENTON WAY
#27-01 SGX CENTRE
SINGAPORE 068807

Date: 01/03/2022
Vehicle No.: SMP-5766-C
Make: HONDA
Model: FIT 1.3 (A)
Chassis No.: GK3-3418358
YoM:

Attention: Motor Claim Department

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	TAILGATE	779.20 \$879.20	DD✓
1	TAILGATE WEATHERSTRIPE	92.30 \$102.30	DIS✓
1	TAILGATE GARNISH	258.00 \$298.40	BR✓
1	TAILGATE LOGO	28.00 \$49.40	} NECV
1	TAILGATE EMBLEM - FIT	28.50 \$55.90	
1	TAILGATE LOCK	90.00 \$217.20	JM✓
1	TAILGATE INNER TRIM BOARD	✓ \$128.20	BR✓
1	TAILGATE DAMPER LH	\$113.20	} NDX
1	TAILGATE DAMPER RH	\$113.20	
2	TAILGATE STOPPER	\$25.80	NNX
1	TAIL GATE INNER LAMP LH	\$109.20	} NDX
1	TAILGATE INNER LAMP RH	\$109.20	
1	REAR BUMPER	510.00 \$629.50	DD✓
1	REAR BUMPER RETAINER LH	25.70 \$38.70	} NECV
1	REAR BUMPER RETAINER RH	25.70 \$38.70	
1	REAR BUMPER DIFFUSER	\$88.40	NDX
1	REAR BUMPER SIDE GARNISH (LH)	\$56.10	NDX
1	END PANEL	341.60 \$490.00	DD✓
1	END PANEL TOP GARNISH	71.60 \$180.60	BR✓
1	REAR FENDER (LH)	\$708.20	BTXR
1	REAR FENDER INNER SHIELD (LH)	99.00 \$113.70	TN✓
1	SPARE TYRE COMPARTMENT BOARD	\$280.70	} NDX
1	SPARE TYRE COMPARTMENT	\$220.40	
1	REAR FENDER INNER TRIM	224.00 \$300.70	BR✓
1	TAIL LAMP (LH)	290.00 \$394.20	BR✓
1	TAIL LAMP RH	290.00 \$394.20	BR✓
1	TAIL LAMP PANEL (LH)	✓ \$125.50	DD✓
Sub Total		3,407.30 \$6,260.80	

@ 20%
681.46
2,725.84

ESTIMATED REPAIR COST DETAILS

ACC22020001

Discount 20% on Parts

(\$1,252.16)

\$5,008.64

Special Nett

1	TAILGATE INNER TRIM BOARD CLIPS SET	30.00	\$50.00	NEC ✓
1	TAILGATE PROTECTOR STRIP	30.00	\$80.00	NEC ✓
1	REAR BUMPER CLIPS SET	30.00	\$50.00	NEC ✓
1	REAR BUMPER REVERSE SENSOR	100.00	\$280.00	SC ✓
1	REAR FENDER MUDGUARD LH		✓\$90.00	BR ✓
Sub Total		280.00	\$550.00	

Labour & Misc

TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS, INCLUSIVE OF REPLACEMENT PARTS	600.00	\$1,000.00	✓
LABOUR TO SPRAY PAINT AFFECTED AREAS TO RUST PROOF AFFECTED AREA	600.00	\$1,200.00	✓
DISMANTLE AND TRANSFER TAILGATE FITTINGS AND MECHANISM TO NEW BOOT LID/FACILITATE REPAIR	80.00	\$100.00	✓
TO PERFORM WATER SEEPAGE TEST AFTER REPAIR		\$60.00	NNX
DISCONNECT AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKET	30.00	\$60.00	✓
REMOVE AND REFIT END PANEL LINING AND GARNISH TO FACILITATE REPAIR		\$80.00	NNX
REMOVE AND REFIT REVERSE SENSOR		\$60.00	✓
TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR	120.00	\$150.00	✓
TO REALIGN REAR EXHAUST SYSTEM		\$80.00	NNX
Sub Total	1430.00	\$2,850.00	

Sub Total \$8,408.64

GST 0%

Total \$8,408.64

Survey 8/2/2022 16.04 hrs
Resurvey 9/2/2022 13.55 hrs
TGM Qm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LS 3600/2

TGM Qm
17/3/2022

Lump sum repairs
Repair days 5

Parts	2725.84
SN	280.00
Labour	1490.00
	4495.84
@ 20%	889.17
	3596.67