



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLF9964K HONDA VEZEL 1.5X CVT ABS DAIRBAG 2WD 5DR

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT	
<u>PARTS (LIST ITEMS)</u>					
1	Front bumper X R	Part Items Total:	521.00		
2	Front bumper side retainer LH/RH @2*\$18 X		36.00		
1	Center grille base am B / CUT		282.00		
1	Center grille outer garnish / CUT		204.00		
2	Center grille side chrome LH/RH @2*\$57 / CUT		114.00		
1	Center grille logo badge / APC		24.00		
			1181.00		
			-20% -236.20		
			944.80		
<u>SPECIAL NETT ITEMS</u>					
1	Front bumper clips X		SN Items Total:	35.00	
1	Center grille clips / AK	30.00			
1	Car plate with holder / CM	35.00 /			
			100.00		
			1044.80		



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 5(608581)

Email: motor@wahhong.sg
(199806235M)

Vehicle No. SLF9964K HONDA VEZEL 1.5X CVT ABS DAIRBAG 2WD 5DR

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	400.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	400.00	200
3	To remove and repair/refit wiring system at accident damaged area and check for all electrical proper function	30.00 ✓	
Labour Total :		830.00	
TOTAL (PARTS & LABOUR):		1874.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are put on "No Prejudice" basis
- Third party survey is on a "No Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)
10/2/22, 9.30am

WZ RL
L/S
hy AL RL
3 L/S