

# JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778  
E-mail:jlperfectautowork@gmail.com



DATE : 04.02.2022

TO : **AIG** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SMV4518C**  
MODEL : **HONDA VEZEL**  
DATE OF ACCIDENT : 01.02.2022  
TIME OF ACCIDENT : 17:10HRS

*Cecilia.*

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	HEADLAMP LH <i>cracked</i>	1	\$ 3,984.60	\$ 3,984.60
2	HEADLAMP LOWER BRACKET LH <i>cracked</i>	1	\$ 52.00	\$ 52.00
3	FRONT BUMPER <i>Delud</i>	1	\$ 878.50	\$ 878.50
4	FRONT BUMPER LOWER LIP <i>new</i>	1	\$ 355.00	\$ 355.00
5	FRONT BUMPER FOGLAMP LH <i>new</i>	1	\$ 327.70	\$ 327.70
6	FRONT BUMPER FOGLAMP COVER LH <i>Delud</i>	1	\$ 69.00	\$ 69.00
7	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 150.00	\$ 150.00
8	FRONT BUMPER SIDE RETAINER <i>2nd AH</i>	2	\$ 23.00	\$ 46.00
9	FRONT BUMPER REINFORCEMENT <i>2 top on</i>	1	\$ 321.00	\$ 321.00
10	FRONT WIPER PANEL GARNISH <i>new</i>	1	\$ 374.40	\$ 374.40
11	FRONT RESORNATOR BOX <i>cracked</i>	1	\$ 210.40	\$ 210.40
12	BONNET <i>new</i>	1	\$ 1,168.00	\$ 1,168.00
13	FRONT FENDER LH <i>Buckled</i>	1	\$ 748.80	\$ 748.80
14	FRONT FENDER INNER GARNISH LH <i>new</i>	1	\$ 85.00	\$ 85.00
15	FRONT FENDER ARCD GARNISH LH <i>let</i>	1	\$ 195.00	\$ 195.00
16	FRONT FENDER INNER COWLING LH <i>form</i>	1	\$ 170.50	\$ 170.50
17	FRONT WHEEL RIM RH <i>new</i>	1	\$ 1,450.00	\$ 1,450.00
18	FRONT ABS SENSOR <i>new</i>	1	\$ 295.00	\$ 295.00
19	FRONT CROSSMEMBER	1	\$ 1,365.00	\$ 1,365.00
20	FRONT STEERING RACK & PINION <i>Not</i>	1	\$ 1,750.00	\$ 1,750.00
21	FRONT SHOCK ABSORBER RH <i>new</i>	1	\$ 586.50	\$ 586.50
22	FRONT LOWER ARM RH	1	\$ 474.70	\$ 474.70
23	FRONT KNUCKLE ARM RH	1	\$ 461.70	\$ 461.70
24	FRONT KNUCKLE ARM INNER BEARING RH	1	\$ 262.00	\$ 262.00

*2335*  
*765*  
*23*  
*586*

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SMV4518C**  
 MODEL : **HONDA VEZEL**  
 DATE OF ACCIDENT : 01.02.2022  
 TIME OF ACCIDENT : 17:10HRS

25	FRONT WHEEL HUP RH <i>2 All</i>	1	\$ 379.40	\$ 379.40	<i>+</i>
26	FRONT LINKAGE RH <i>1 new</i>	1	\$ 65.00	\$ 65.00	<i>+</i>

*4519.40*  
*3615.52*

TOTAL PRICE	\$ 16,225.20
LESS 20%	\$ 3,245.04
<b>SUB TOTAL PRICE</b>	<b>\$ 12,980.16</b>

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
2	FRONT BUMPER LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
3	FRONT WIPER PANEL GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
4	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
5	BONNET SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
6	FRONT FENDER INNER GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
7	FRONT FENDER ARCED GARNISH CLIP LH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>20</i>
8	FRONT FENDER INNER COWLING CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
9	SIDE SKIRT CLIP RH <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
10	WHEEL CAP (SET) <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
11	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 450.00	\$ 450.00	<i>+</i>
12	FRONT WHEEL RIM RH <i>new</i>	1	\$ 1,500.00	\$ 1,500.00	<i>+</i>
13	BRAKE OIL <i>new</i>	1	\$ 40.00	\$ 40.00	<i>+</i>

**TOTAL \$ 2,630.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>600</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>80</i>
4	WIRING CHECK	\$ 120.00	<i>30</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>X</i>
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>X</i>
7	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	<i>X</i>

*80*

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SMV4518C**  
 MODEL : **HONDA VEZEL**  
 DATE OF ACCIDENT : 01.02.2022  
 TIME OF ACCIDENT : 17:10HRS

8	FOUR WHEEL ALIGNMENT	\$ 120.00	x
9	RESET ABS LIGHT	\$ 350.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

1310

**TOTAL \$ 7,220.00**

TOTAL PARTS COST : \$ 15,610.16  
 TOTAL LABOUR COST : \$ 7,220.00  
 TOTAL REPAIR COST : \$ 22,830.16

Adnan G  
 L/S 05/02/22  
 04 Days

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

total: 5025.52

L/S: AK

AK

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: