



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CS/EQI22001181/Ktf3n2 Date: 10/03/2022 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 4711U	Veh. Inspected	SGU 9403T	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM22HO00174/JT	Excess (\$)	0.00	
Assign From	JAIME TAY	Assign Date	08/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE (A)	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	AGH300040221	Colour	METALLIC BLACK	
Odometer	160142 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	BRIDGESTONE	8 mm	
L/H Front Tyre	235/50 R18	BRIDGESTONE	8 mm	
R/H Rear Tyre	235/50 R18	BRIDGESTONE	8 mm	
L/H Rear Tyre	235/50 R18	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/02/2022	Inspection Date	09/02/2022	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	