



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2201306

INV Date 10/03/2022

Reference CS/EQI22001181/Ktf3n2

Code EQI

### PROFESSIONAL SERVICE FEE

Vehicle No. SGU 9403T

Insured Veh. GBG 4711U

Claim No. DM22HO00174/JT

Policy No.

Accident Date 04/02/2022

Inspection Date 09/02/2022

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**HYN**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: CS/EQI22001181/Ktf3n2 Date: 10/03/2022 Code: EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBG 4711U	Veh. Inspected	SGU 9403T
Policy No.		Coverage (\$)	0.00
Claim No.	DM22HO00174/JT	Excess (\$)	0.00
Assign From	JAIME TAY	Assign Date	08/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA VELLFIRE (A)	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	AGH300040221	Colour	METALLIC BLACK
Odometer	160142 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	BRIDGESTONE	8 mm
L/H Front Tyre	235/50 R18	BRIDGESTONE	8 mm
R/H Rear Tyre	235/50 R18	BRIDGESTONE	8 mm
L/H Rear Tyre	235/50 R18	BRIDGESTONE	8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	04/02/2022	Inspection Date	09/02/2022
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 9403T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR TAILGATE	BENT	1,980.70	1,718.00
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	145.70	145.70
1	REAR TAILGATE "VELLFIRE" EMBLEM	NECESSARY	87.20	87.20
1	REAR TAILLAMP OUTER LH	MTG CRACKED	575.50	575.50
1	REAR SIDE GARNISH LH	BUCKLED	355.10	355.10
1	REAR BUMPER	BUCKLED	1,800.70	1,217.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	135.60	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	95.10	-
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-1,293.90	-1,024.63
			3,881.70	3,073.87
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR TAILLAMP OUTER CLIPS LH (SN)	NOT NECESSARY	20.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	300.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
			450.00	90.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF REAR FENDER LH AND REAR END PANEL.		1,000.00	400.00
	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS.		1,000.00	650.00
	TO TUFF KOTE & UNDERSEAL MATERIALS.		100.00	30.00
	TO DISMANTLE & REPLACED REAR TAILGATE INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION.		120.00	60.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS & ETC. TO EFFECT AT ACCIDENT AREAS.		150.00	120.00

Report Ref No. CS/EQI22001181/Ktf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DIAGNOSIS FAULT CODE & RESET MEMORY.	NOT NECESSARY	100.00	-
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		80.00	20.00
			2,550.00	1,280.00
GRAND TOTAL			6,881.70	4,443.87
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,550.00

Report Ref No. CS/EQI22001181/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	04/02/2022 16:27 (SGT)
Date of Accident	04/02/2022 08:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE TAMPINES AVE 5 EXIT
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU9403T
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	XIN YE
NRIC No	S8173854H
Email Address	XINYE@OCO.COM.SG
Mobile Phone No	(Phone) +65-91839579
Alternative Phone No	(Office) +65-91839579

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Vellfire
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2500

### INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	B300207512 QMY
Cover Note Number	-

### DRIVER

Name of Driver	XIN YE
NRIC No	S8173854H

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

3  
10:11 am  
4 Feb 2022



Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**

← Taylor Ave 5

Exit  
Zebra  
Crossing



A: SGU 9403T

B: G8G 4711U

C: SKL 821D





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SGU 9403T

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGU 9403T

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SGU 9403T**

**RE-INSPECTION**

