

## Vehicle Damage Assessment Report for [SNC8808C]

Estimate Created: 08/02/2022 08:35 by Insurlogic 1 (Insurlogic\_Pte\_Ltd)

Owned: 06/10/2022 12:41 by To\_Be\_Assigned (Insurlogic\_Pte\_Ltd)

### General Information

Insurance Company	India International Insurance	Claim Number
Claim Type	TP	
Workshop	Insurlogic_Repair_Shop	Reference Number

### Vehicle Information

Brand	BMW	Model	5-Series
Engine Type			
License Plate Number	SNC8808C	VIN (or Chassis #)	

### Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

### Comments

- Final review based on information provided by LKK Auto Consultants PTE LTD: Concluded lump sum repair cost of \$8422.60 with 5 working days.	Insurlogic 4 (06/10/2022 12:40)
- Pre Estimate of the repair cost base on photos provided in GIA report	Chee_Wee_Tay (08/02/2022 11:20)

**Materials**

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
SUNDRIES		1.0	150.00	0.00 %	150.00
TAILGATE ALUMINIUM		1.0	1818.60	0.00 %	1,818.60
REAR BUMPER BOTTOM REINFORCEMENT		1.0	75.95	0.00 %	75.95
REAR BUMPER PANEL PRIMED (PD)		1.0	1603.00	0.00 %	1,603.00
LETTERING 520I		1.0	65.60	0.00 %	65.60
PLAQUE 82MM		1.0	72.85	0.00 %	72.85
GROMMET		1.0	1.60	0.00 %	1.60
EXPANDING RIVET D=8MM		1.0	11.00	0.00 %	11.00

Materials Subtotal      3,798.60

**Labor****Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
TO REPLACE REAR BUMPER, BOOT LID INCLUDING KNOCK OUT DENTED AREA	RnR	1700.00	0.00 %	1,700.00
TO CARRY OUT BODY CAVITY PRESERVATION	RnR	112.00	0.00 %	112.00
TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	RnR	168.00	0.00 %	168.00
TO TRANSFER OLD MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	RnR	504.00	0.00 %	504.00
TO CHECK ELETRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	RnR	168.00	0.00 %	168.00

**Paint**

Description	Paint Type	Cost	Markup/Disc %	Price
TO RESPRAY REAR BUMPER AND BOOT LID	Full spray	1972.00	0.00 %	1,972.00

Labor Rate                      S\$ 50 / Hour

General Labor Subtotal      2,652.00

Paint Labor Subtotal      1,972.00

Labor Subtotal      4,624.00

Summary

---

Repair Cost	8,422.60
Discount(0 %)	(0.00)
	8,422.60
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	8,422.60