

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

260, Tampong Arang Road
East Coast Centre
Singapore 436180
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

25/2/2022 ✓
2pm - 3pm
Shij only



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 60826 Date Estimated : 07/02/2022 Prepared By : Chua Kee Sin	Page No. : 1 of 5
--	-------------------

- ESTIMATE REPAIR FOR - Tan Tze Woon (Chen ZhiWen) 21 Tampines Street 34 #07-04 Singapore 529232	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNC8808C	WBAJA12070WW34954	26/06/2019	520i	71771

DESCRIPTION	VALUE
To replace rear bumper, boot lid including to knock out dented area <i>880 X 2</i>	<i>1700</i> - 2,550.00
To respray rear bumper and boot lid	<i>1972</i> - 2,076.00
To carry out body cavity preservation. (Per panel).	<i>112</i> - 118.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	<i>16f</i> - 177.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	<i>504</i> - 531.00
To check electrical wiring system and lighting at the rear section for proper function.	<i>16f</i> - 177.00
Sundries.	<i>9</i> - 150.00
Total Labour 1:	5,779.00

DESCRIPTION	QTY	PRIC	VALUE
TAILGATE ALUMINIUM <i>00</i>	1	1,818.60	1,818.60
REAR BUMPER CARRIER <i>1 + nn</i>	1	582.55	582.55
REAR BUMPER BOTTOM REINFORCEMENT <i>BR</i>	1	75.95	75.95
REAR BUMPER CENTRE GUIDE <i>1 + nn</i>	1	177.25	177.25
REAR BUMPER TRIM STRIP <i>1 + nn</i>	1	119.40	119.40
# REAR BUMPER PANEL PRIMED (PD) <i>00</i>	1	1,603.00	1,603.00
LETTERING 520I <i>1</i>	1	65.60	65.60
PLAQUE 82MM <i>1</i>	1	72.85	72.85
GROMMET <i>2</i>	2	0.80	1.60
EXPANDING RIVET D=8MM <i>10</i>	10	1.10	11.00
UNDERBODY PANELLING REAR <i>1</i>	1	48.95	48.95
DECOUPING RING PDC TORQUE CONVERTER <i>2</i>	2	5.15	10.30

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64756624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 60826
Date Estimated : 07/02/2022
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNC8808C	WBAJA12070WW34954	26/06/2019	5201	71771

DESCRIPTION	QTY	PRIC	VALUE
ULTRASONIC SENSOR MINERALWEISS(WA96) *nn	2	371.20	742.40
Total Parts :			5,329.45

Steve (LKK) 25/2/22, 3-M/L

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To declare any defects before survey
- Parts must be replaced on a like-for-like basis
- Third party claims must be on a like-for-like basis
- No legal proceedings to be initiated
- Supplementary work must be approved by the insurance company and is subject to their approval from the insurance company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess S\$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

PIP, My BL 14
5 days



Labour 1	:	5,779.00
Parts	:	5,329.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	777.59
Grand Total	:	11,886.04

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **