

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 60826**
Date Estimated : **07/02/2022**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Tan Tze Woon (Chen ZhiWen)
21 Tampines Street 34
#07-04

Singapore 529232

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNC8808C	WBAJA12070WW34	26/06/2019	520i	75803

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper, boot lid including to knock out dented area	1,700.00	0.00	1,700.00
To respray rear bumper and boot lid	1,972.00	0.00	1,972.00
To carry out body cavity preservation. (Per panel).	112.00	0.00	112.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	504.00	0.00	504.00
To check electrical wiring system and lighting at the rear section for proper function.	168.00	0.00	168.00
Sundries.	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
TAILGATE ALUMINIUM	1,818.60	1.00	0.00	1,818.60
REAR BUMPER BOTTOM REINFORCEMENT	75.95	1.00	0.00	75.95
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,603.00	1.00	0.00	1,603.00
LETTERING 520I	65.60	1.00	0.00	65.60
PLAQUE 74MM	72.85	1.00	0.00	72.85
GROMMET	0.80	2.00	0.00	1.60
EXPANDING RIVET D=8MM	1.10	10.00	0.00	11.00

SUPPLEMENTARY ITEMS

Total Labour :	4,774.00
Total Parts :	3,648.60
Total Labour & Parts :	8,422.60
Deduction for Excess :	
Total Repair Costs less Excess:	8,422.60
GST @7%:	589.58
Grand Total :	9,012.18

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

LOSS OF USE=\$120X5
LTA SEARCH FEE=\$7.45