

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 21 Mar 2022

Preliminary Advice

Insured : SMG2552U

Vehicle No

TP Vehicle : SJZ7257A
No

Accident Date : 22/01/2022

Make : HONDA FIT

Assignment Date : 08/02/2022

Date of : 10/02/2022
Inspection

Est. Duration of : 5
Repair

Inspection At : YEW TEE AUTOMOBILE TECH PTE LTD (KAKI BUKIT)
BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI
BUKIT
SINGAPORE 417800

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,790.00
Revised Amount	:S\$	3,330.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,330.40

Lump Sum Repair	:S\$	2,650.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.