

## REPAIR DETAILS

| Estimates On Parts |     |                                       | Amount     | %Disc  | After Disc             |
|--------------------|-----|---------------------------------------|------------|--------|------------------------|
| No.                | Qty | Particulars                           |            |        |                        |
| 1                  | 1   | FRONT DOOR RH                         | 900.00     | -20.00 | 720.00 <i>KR</i>       |
| 2                  | 1   | FRONT DOOR OUTER HANDLE RH            | 110.00     | -20.00 | 88.00 <i>KR</i>        |
| 3                  | 1   | FRONT DOOR SIDE MIRROR RH             | 350.00     | -20.00 | 280.00 <i>jam</i>      |
| 4                  | 1   | FRONT DOOR SIDE MIRROR REAR COVER RH  | 100.00     | -20.00 | 80.00 <i>mis</i>       |
| 5                  | 1   | FRONT DOOR SIDE MIRROR SIGNAL LAMP RH | 80.00      | -20.00 | 64.00 <i>SVC</i>       |
| 6                  | 1   | ROCKER PANEL RH                       | 0.00       | 0.00   | 0.00 <i>X SVC</i>      |
| 7                  | 1   | FRONT DOOR GLASS REGULATOR RH         | 380.00     | -20.00 | 304.00 <i>X SVC</i>    |
| 8                  | 1   | FRONT DOOR GLASS MOTOR RH             | 550.00     | -20.00 | 440.00 <i>DI</i>       |
| 9                  | 1   | FRONT FENDER RH                       | 450 550.00 | -20.00 | 440.00 <i>cut</i>      |
| 10                 | 1   | FRONT BUMPER                          | 503 600.00 | -20.00 | 480.00 <i>nel</i>      |
| 11                 | 1   | FRONT BUMPER SIDE RETAINER RH         | 70.00      | -20.00 | 56.00 <i>scr</i>       |
| 12                 | 1   | FRONT HEADLAMP RH                     | 570 780.00 | -20.00 | 624.00 <i>DIS</i>      |
| 13                 | 1   | FRONT FENDER INNER SHIELD RH          | 90 230.00  | -20.00 | 184.00                 |
| Total Parts (S\$)  |     |                                       |            |        | 3,760.00 <i>1690.4</i> |

| Estimates of Miscellaneous Items |     |                    | Amount | %Disc | After Disc            |
|----------------------------------|-----|--------------------|--------|-------|-----------------------|
| No.                              | Qty | Particulars        |        |       |                       |
| 1                                | 1   | FRONT WHEEL RIM RH | 850.00 | 0.00  | 850.00 <i>scr 280</i> |
| 2                                | 1   | FRONT TYRE RH      | 220.00 | 0.00  | 220.00 <i>X SVC</i>   |
| Sub Total (S\$)                  |     |                    |        |       | 1,070.00              |

| Estimates On Labour     |     |                                                                                                                                                                                       | Amount | %Disc | After Disc                  |
|-------------------------|-----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|-------|-----------------------------|
| No.                     | Qty | Particulars                                                                                                                                                                           |        |       |                             |
| 1                       | 1   | To Reset Power Window.                                                                                                                                                                | 120.00 | 0.00  | 120.00 <i>XNN</i>           |
| 2                       | 1   | To Transfer Door.                                                                                                                                                                     | 80.00  | 0.00  | 80.00 <i>XNN</i>            |
| 3                       | 1   | To Conduct Computer Wheel Alignment.                                                                                                                                                  | 80.00  | 0.00  | 80.00 <i>60 need report</i> |
| 4                       | 1   | To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.                                                                                    | 30.00  | 0.00  | 30.00 <i>20</i>             |
| 5                       | 1   | To Dismantle and Refit Front Undercarriage.                                                                                                                                           | 220.00 | 0.00  | 220.00 <i>XNN</i>           |
| 6                       | 1   | To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools. | 800.00 | 0.00  | 800.00 <i>650</i>           |
| Gross Labour Cost (S\$) |     |                                                                                                                                                                                       |        |       | 1,330.00                    |

| Estimates On Paint Work Labour |     |                                                                                                                                      | Amount | %Disc | After Disc          |
|--------------------------------|-----|--------------------------------------------------------------------------------------------------------------------------------------|--------|-------|---------------------|
| No.                            | Qty | Particulars                                                                                                                          |        |       |                     |
| 1                              | 1   | To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.                                                       | 30.00  | 0.00  | 30.00 <i>✓</i>      |
| 2                              | 1   | To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and | 600.00 | 0.00  | 600.00 <i>X 625</i> |
|                                |     |                                                                                                                                      |        |       | 2650                |