

TPAXA

VECON

SJZ92596 2011 Jan.

Mercedes Benz E250

WDD2120472A359311

Front RH Door	Dented	2070	2120
Front RH Door Lock	NH M	398	X
Front RH Door Weatherstripe	NH	280	✓
Front RH Door Chrome Moulding	Lt	93	✓
Front RH Door Outer Handle	Rep's	385	X

Rear RH Door	Dented	2125	2175
Rear RH Door Lock	NH M	390	X
Rear RH Door Weatherstripe	NH	285	✓
Rear RH Door Chrome Moulding	Lt	98	✓

Rocker Panel Side Skirting Rep's 692 X

Rocker Panel Side Skirting Clips. ^{NH} 50(SN) X

Rear RH Wheel Rim. NH M 1250 X

Rear RH Tyre. NH M 300(SN) X

SJZ9259G.

Rear Bumper Repair 1680 X

Rear Bumper Lips ^{HP} _{air} 50(SN) X

Rear Bumper Side Holder RH. ^{NT} ~ 78 X

5341

4806.90

Panel Beating

1000 ~~500~~ 600

Spray Painting.

1200 ~~900~~ 1000

Wiring.

~~50~~ 30

To transfer front end }
rear door fittings } 1590

~~300~~ ~~160~~ 200

To perform wheel alignment.

150 X

To remove reverse sensor

120. X

13,144.00

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6396.90

2/8/15 5.1K.

05 Days.