

TPAXA

VECON

SJZ92596 2011 Jan.

Mercedes Benz E250

WDD2120472A359311

Front RH Door	Dented	2070.	✓
Front RH Door Lock	XHE M	398	X
Front RH Door Weatherstripe	Ner	280	✓
Front RH Door Chrome Moulding	lt	93.	✓
Front RH Door Outer Handle	Reis	385	X
Rear RH Door	Dented	2125	✓
Rear RH Door Lock	XHE M	390	✓
Rear RH Door Weatherstripe	Ner	285.	✓
Rear RH Door Chrome Moulding	lt	98	✓
Rocker Panel Side Skirting	Reis	692	X
Rocker Panel Side Skirting Clips	XHE M	50(SN)	X
Rear RH Wheel Rim	XHE M	1250	X
Rear RH Tyre	Ner	300(SN)	X

SJZ9259G.

Rear Bumper Repair 1680 X

Rear Bumper Lips ^{NH} _{air} 50(su) X

Rear Bumper Side Holder RH. ^{NH} ~ 78 X

5341

4806.90

Panel Beating

1000 500

Spray Painting.

1200 900.

Wiring.

~~50~~ 30

To transfer front end }
rear door fittings } 1590

~~300~~ 160

To perform wheel alignment.

150 X

To remove reverse sensor

120. X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6396.90

2/81 5.1K.

05 Days.