

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



Cecilie

DATE : 07.02.2022

SALCA2A XOK H8 09433

TO : **AXA** MOTOR CLAIMS DEPTS
VEHICLE NO : **SFM7813K**
MODEL : **LAND ROVER RANGE ROVER DISCOVERY SPORT**
DATE OF ACCIDENT : 06.02.2022
TIME OF ACCIDENT : 13:59HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	TAILGATE	1	\$ 3,884.40	\$ 3,884.40	+
2	TAILGATE OUTER GRANISH	1	\$ 384.00	\$ 384.00	+
3	TAILGATE LOGO	1	\$ 258.00	\$ 258.00	+
4	TAIGATE EMBLEM 'RANGE ROVER'	1	\$ 258.00	\$ 258.00	+
5	TAIGATE EMBLEM 'SPORT'	1	\$ 135.00	\$ 135.00	+
6	TAILGATE INNER LOCK	1	\$ 684.00	\$ 684.00	+
7	TAILGATE INNER TRIM	1	\$ 689.00	\$ 689.00	+
8	TAILGATE WEATHERSTRIP	1	\$ 384.00	\$ 384.00	+
9	TAILGATE WINDSCREEN MOULDING	1	\$ 215.00	\$ 215.00	+
10	TAILGATE SMART OPEN SENSOR	1	\$ 489.00	\$ 489.00	+
11	TAILGATE DETECTOR	1	\$ 148.00	\$ 148.00	+
12	TAIL LAMP	2	\$ 1,953.00	\$ 3,906.00	+
13	TAIL LAMP BRACKET	2	\$ 374.00	\$ 748.00	+
14	REAR BUMPER CENTER <i>Deformed</i>	1	\$ 2,109.00	\$ 2,109.00	+
15	REAR BUMPER SIDE <i>Not New</i>	2	\$ 745.40	\$ 1,490.80	+
16	REAR BUMPER TOWING COVER <i>Not Nec</i>	1	\$ 105.00	\$ 105.00	+
17	REAR BUMPER LOWER DIFFUSER <i>Deformed</i>	1	\$ 798.00	\$ 798.00	—
18	REAR BUMPER SIDE DIFFUSER <i>emb'd.</i>	2	\$ 520.00	\$ 1,040.00	—
19	REAR BUMPER SIDE RETAINER <i>Not New</i>	2	\$ 241.00	\$ 241.00	+
20	REAR BUMPER CENTER FRAME <i>Not New</i>	1	\$ 356.00	\$ 712.00	+
21	REAR BUMPER REFLECTOR <i>LH comb'd</i>	2	\$ 158.00	\$ 316.00	158
22	REAR BUMPER REINFORCEMENT <i>Pented</i>	1	\$ 898.10	\$ 898.10	620
23	REAR BUMPER REINFORCEMENT BRACKET <i>Not New</i>	2	\$ 154.00	\$ 308.00	+
24	REAR BUMPER REVERSE SENSOR <i>2 pieces changed</i>	4	\$ 315.00	\$ 1,260.00	630
25	REAR BUMPER REVERSE SENSOR HOLDER <i>New</i>	4	\$ 63.40	\$ 253.60	+
26	REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>Not New</i>	1	\$ 583.70	\$ 583.70	+
27	REAR END PANEL (OUTER) <i>Repair</i>	1	\$ 1,481.90	\$ 1,481.90	+

28	REAR END PANEL TOP GARNISH <i>Not New</i>	1	\$ 425.00	\$ 425.00	X
29	REAR FENDER WHEEL ARCH GARNISH <i>Not New</i>	2	\$ 359.00	\$ 718.00	X
30	REAR FENDER COWRING <i>x/c new</i>	2	\$ 680.00	\$ 1,360.00	X
31	REAR EXHUAUST HEAT SHIELD (BUMPER) <i>torn</i>	1	\$ 356.00	\$ 356.00	✓
32	REAE EXHUAUST CHROME <i>x/c new</i>	2	\$ 389.00	\$ 778.00	X
33	REAR FLOOR PANEL TOP BOARD <i>Not New</i>	1	\$ 956.00	\$ 956.00	X
34	REAR FLOOR PANEL TOOLS SPONGE <i>Not New</i>	1	\$ 584.00	\$ 584.00	X

5964.60
5368.14

TOTAL PRICE	\$ 28,956.50
LESS: 10%	\$ 2,895.65
SUB TOTAL PRICE	\$ 26,060.85

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Not New</i>	1	\$ 50.00	\$ 50.00	X
2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
3	REAR FENDER COWRING CLIP (SET) <i>x/c new</i>	1	\$ 80.00	\$ 80.00	X
4	REAR FENDER WHEEL ARCH GARNISH CLIP (SET) <i>x/c Not New</i>	1	\$ 60.00	\$ 60.00	X
6	TAIL LAMP CLIP (SET) <i>Not New</i>	1	\$ 60.00	\$ 60.00	X
7	TAILGATE SEALANT <i>Not New</i>	1	\$ 150.00	\$ 150.00	X
8	TAILGATE INNER BOARD CLIP (SET) <i>2</i>	1	\$ 80.00	\$ 80.00	X
9	TAILGATE WINDSCREEN SEALANT <i>Not New</i>	1	\$ 80.00	\$ 80.00	X
10	TAILGATE WINDSCREEN INNER SEAL <i>Not New</i>	1	\$ 60.00	\$ 60.00	X
13	REAR END PANEL (OUTER) SEALANT	1	\$ 150.00	\$ 150.00	
TOTAL				\$ 850.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 1,800.00	400
2	<i>Spray Painting</i> PANEL BEATING AND REPLACE PARTS	\$ 1,600.00	400 400
3	<i>Wiring</i> SPRAY PAINTING TO AFFECTED AREA	\$ 180.00	30
4	TRANSFER TAILGATE MECHAISM	\$ 80.00	X
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	X
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	60
9	REMOVE AND REFIX CAR VIDEO RECORDER	\$ 80.00	X

