

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

7-Jan-22

Our ref : TP/5084/22

Yin Lai Yee Oo

TP China.

Guilin.

RE : Estimate cost for vehicle no : SMS 494D

1 pc	frt lh door	Distorted.	\$	848.30	✓
1 pc	frt lh door outer handle	Damaged		398.90	128. ✓
1 pc	frt lh door switch	Damaged		25.40	✓
2 pcs	frt lh door hinges	New		78.40	X
2 pcs	frt lh door sticker	New		71.60	✓
1 pc	frt lh door outer moulding	Behind		68.30	✓
1 pc	frt lh door w/strip	At		131.00	✓
1 pc	frt lh door trimboard	Crushed		491.50	✓
1 pc	frt lh door lock	Damaged		212.90	✓
1 pc	frt lh door channel	Best		149.00	✓
1 pc	frt lh wing mirror	New		573.30	X
1 pc	frt lh door regulator gear	3 Damaged		368.90	265
1 pc	frt lh door regulator gear motor			416.50	348. ✓
1 pc	rear lh door	Distorted		895.60	✓
2 pcs	rear lh door hinges	Best		78.40	✓
1 pc	rear lh door w/strip	At		158.50	✓
1 pc	rear lh door catch	New		27.70	X
1 pc	rear lh door outer moulding	New		48.40	X.
2 pcs	rear lh door sticker	New		50.80	✓
1 pc	rear lh door rubber	At		117.70	✓
1 pc	rear lh door lock	Damaged		212.90	✓
1 pc	rear lh door regulator gear	Damaged		178.50	✓
1 pc	rear lh door regulator gear motor	New		328.90	X.
1 pc	rear lh door trimboard	Crushed		431.20	✓
1 pc	lh centre door pillar	Repair		795.30	X
1 pc	rear lh fender	Dented		826.60	✓
1 pc	lh taillamp	New		255.60	X
1 pc	rear bumper	Behind		819.40	495. ✓
1 pc	rear bumper lh retainer	New		18.00	✓
7 pcs	rear bumper clips	New		27.30	✓
1 pc	rear bumper inner garnish	New		60.80	X.
1 pc	rear lh rim	At		477.70	✓
1 pc	lh rocker panel	Repair		228.90	X
				9,872.20	

6707.20

5365.76

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : Estimate cost for vehicle no : SMS 494D

Bal brought forward:	\$	9,872.20
less 20%		<u>1,974.44</u>
		7,897.76
1 pc rear lh tyre <i>new</i>		300.00 snett <i>X</i>
Panel beating.	<i>2390</i>	1,200.00 <i>1000</i>
Spray painting.		1,700.00 <i>1200</i>
Transfer 2 doors parts.		200.00 <i>160</i>
Wiring.		<u>30.00</u> ✓
		11,327.76
Plus 7% GST		<u>792.94</u>
		<u>12,120.70</u>

SD : Twelve thousand one hundred twenty & cents seventy only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling

2/s 07/02/22.

10 Days.

Total: 7755.76

4/s: 6.2k.