

CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD  
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897  TEL: 67143369  Contact No	Cust No/Name /Cycle & Carriage, Fulco Motor De Reg No/Reg Date GBL1784C / 30/03/2021 Date In/Mileage 17/01/2022/ 6319 Chassis No VR7EFYH2RMJ542597 Engine No 10Q4DR0030181 Make/Model CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13 Colour/Trim WPP / GY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000051	Credit	31/01/2022/ 08:49	OD	303 / Renemer	25421

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC/SCANNING				250.00
S MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON LHF ACCIDENT AFFECTED AREAS				80 100.00
S MIPNT88088 TO REMOVE & RE-INSTALL ROOF LINING, TRIMMING & CARPETS TO FACILITATE REPAIR ON LHF ACCIDENT AFFECTED AREAS		640		1280.00
S MIPNT88088 TO TRANSFER LHF DOOR COMPONENTS & MECHANISM PARTS				640.00
S MIPNT88088 TO REMOVE & REPLACE DASHBOARD AND OTHER RELATED PARTS				320 1280.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW & REPAIR PANELS				200 300.00
S MIPNT88088 TO REPLACE LH HEADLAMP, FRONT BUMPER, LH FENDER, LHF DOOR, ETC -TO CUT & WELD LH A PILLAR POST -TO REPAIR INR FRAME AND SIDE SILL STRAIGHTEN, REFORM, ALIGN ON LHF ACCIDENT AFFECTED AREAS				4480 5120.00 2560
S MIPNT98088 SPRAY PAINTING ON LHF ACCIDENT AFFECTED AREAS (FRONT BUMPER, LHF FENDER, LHF DOOR, LH A PILLAR, SIDE SILL & INR FRAME)				4400.00 2750
S MIPNT88088 TO REPLACE CROSSMEMBER AND OTHER SUSPENSION PARTS				640 1920.00
S MIPNT88088 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT				180.00
S MIPNT88088 WHEEL BALANCING (TO REPLACE 1 PC TYRE & RIM)				50.00
M SUNDRY 205/60 R16 TYRE				127.6 142.00
M SUNDRY COMPANY STICKER				180 50.00
M C9816824180 LH HEADLIGHT ASSEMBL	1.00	622.00	0.00	622.00
M C1632656780 UPR FRONT BUMPER	1.00	580.00	0.00	580.00
M C9816765680 LWR FRONT BUMPER	1.00	613.00	0.00	500 X 613.00


Confirm &amp; accepted by

640

550

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

### ESTIMATE


Invoice Name & Address	Owner Name & Vehicle Info
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897  TEL: 67143369  Contact No	Cust No/Name /Cycle & Carriage.Fulco Motor De Reg No/Reg Date GBL1784C / 30/03/2021 Date In/Mileage 17/01/2022/ 6319 Chassis No VR7EFYHCRMJ542597 Engine No 10Q4DR0030181 Make/Model CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13 Colour/Trim WPP / GY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000051	Credit	31/01/2022/ 08:49	00	303 / Renemer	25421
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M C9830100580	FR BUMPER INR FRAME	1.00	285.00	0.00	285.00
M C9821847480	LH FRONT BUMPER BRAC	1.00	105.00	0.00	105.00
M C1632655880	SET BUMPER LAT REINF	1.00	147.00	0.00	147.00
M C9830512680	FRONT PANEL CROSSMEM	1.00	201.00	0.00	201.00
M C9830522280	LH BRACKET CROSSMEMB	1.00	105.00	0.00	105.00
M C9827055880	LHF UNIT FACING SUPP	1.00	201.00	0.00	201.00
M C9817397480	LH COOL AIR ANTI-REC	1.00	106.00	0.00	106.00
M C9816482780	LHF FENDER WING	1.00	434.00	0.00	434.00
M C9817764880	LHF FENDER SUPPORT A	1.00	189.00	0.00	189.00
M C98176914XT	LH DRIP MOULDING	1.00	87.00	0.00	87.00
M C632563	LH SIDE FLASH-UNIT	1.00	27.00	0.00	27.00
M C9821868680	LHF FENDER REAR SEAD	1.00	217.00	0.00	217.00
M C9817398580	LH WHEEL HOUSING MUD	1.00	170.00	0.00	170.00
M C9816437980	LH PASS-COMP-FR STR	1.00	185.00	0.00	185.00
M C9820423380	LH FRONT DOOR	1.00	1462.00	0.00	1462.00
M C98176963XT	LH DOOR PROTECTOR	1.00	336.00	0.00	336.00
M C9820661380	LH FR DOOR W/STRIP O	1.00	79.00	0.00	79.00
M C9817683280	LH RR DOOR W/STRIP	1.00	93.00	0.00	93.00
M C9825723980	LH FR INR DOOR W/STR	1.00	124.00	0.00	124.00
M C1606475180	LH UPR HINGE DOOR	1.00	124.00	0.00	124.00
M C9035AZ	LH LWR HINGE DOOR	1.00	124.00	0.00	124.00
M C9816977280	DOOR ARRESTER	1.00	111.00	0.00	111.00
M C98167912ZD	LH DOOR TRIM LINING	1.00	495.00	0.00	495.00
M C98167928ZD	LH DOOR TRIM CHEATER	1.00	39.00	0.00	39.00
M C9819576080	LH INR SEALING DOOR	1.00	50.00	0.00	50.00
M C9827671580	LH SIDE PASSENGER CO	1.00	2233.00	0.00	2233.00
M C9817300980	WINDOW WASHER RESERV	1.00	232.00	0.00	232.00
M C9816645880	WASHER PIPE SCREENWA	1.00	57.00	0.00	57.00
M C9804681780	FUSE BOX SUPPORT	1.00	58.00	0.00	58.00
M C98153116VT	STEEL WHEEL	1.00	195.00	0.00	195.00
M C98083420XT	WHEEL CAP	1.00	56.00	0.00	56.00
M C9833306080	LHF SHOCK ABSORBER	1.00	225.00	0.00	225.00
M C9678782580	ROD PROTECTOR SHOCK	1.00	13.00	0.00	13.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD  
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897  TEL: 67143369  Contact No	Cust No/Name /Cycle & Carriage, Fulco Motor De Reg No/Reg Date GBL1784C / 30/03/2021 Date In/Mileage 17/01/2022/ 6319 Chassis No VR7EFYH2RMJ542597 Engine No 10Q4DR0030181 Make/Model CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13 Colour/Trim WPP / GY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000051	Credit	31/01/2022/ 08:49	OD	303 / Renemer	25421

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M C9800479780 SPRING SHOCK-ABSORBE	1.00	106.00	0.00	SVC 106.00
M C1647857180 LHF FRONT KNUCKLE ST	1.00	715.00	0.00	715.00
M C9815014680 LHF LWR ARM WISHBONE	1.00	489.00	0.00	489.00
M C9831088880 LHF BALL JOINT SUSPE	1.00	53.00	0.00	53.00
M C9833984280 FRONT ANTI-ROLL BAR	1.00	508.00	0.00	508.00
M C9831547080 LHF ANTI-ROLL BAR LI	1.00	78.00	0.00	78.00
M C1675954280 STEERING RACK ASSY	1.00	2422.00	0.00	2422.00
M C9677071880 FRONT SUBFRAME CROSS	1.00	1122.00	0.00	1122.00
M C1636275820 OTR DASHBOARD INST C	1.00	318.00	0.00	SVC 318.00
M C163627592D LH OTR DASHBOARD INS	1.00	109.00	0.00	SVC 109.00
M C981845422D CTR OTR MLDG PANEL F	1.00	133.00	0.00	133.00
M C982534232D OTR UPR CTR MLDG PAN	1.00	153.00	0.00	153.00
M C166419002D DASHBOARD	1.00	3686.00	0.00	3686.00
M C981655332D LH SIDE COVER-MTG	1.00	62.00	0.00	62.00
M C981943822D LH CTR COVER CONSOLE	1.00	16.00	0.00	16.00
M C9821348980 LHF AIR DUCT DASHBOA	1.00	95.00	0.00	95.00
M C981838072D INR GLOVE BOX FASCIA	1.00	229.00	0.00	229.00
M C982538812D MLDG GLOVE BOX	1.00	140.00	0.00	140.00
M C98253899VH UPR GLOVE BOX FASCIA	1.00	449.00	0.00	449.00

Z NOTES

ACCIDENT ON 17/01/2022 ALONG UPPER THOMSON ROAD

OWNER CLAIMING OWN POLICY

EXCESS AND AUTHORIZATION WILL BE ADVISE BY THE INSURANCE COMPANY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Thuan@Lthauto-lom  
82235769  
10/2/22 0945  
excess TBC  
PIP 6days wp


F: 26954.8  
RD: 15

40045

Confirm & accepted by	Acknowledged by Repairer Signature: Date:	Parts 21,263.00 Labour 0.00 Standard Menu 0.00 Specialist Job 15,520.00 Others(Lub,etc) 0.00 Sundry 192.00 Total(w/o GST) 36,975.00
-----------------------	---	---

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897  TEL:67143369  Contact No	<table> <tr> <td>Cust No/Name</td><td>/Cycle &amp; Carriage, Fulco Motor De</td></tr> <tr> <td>Reg No/Reg Date</td><td>GBL1784C / 30/03/2021</td></tr> <tr> <td>Date In/Mileage</td><td>17/01/2022/ 6319</td></tr> <tr> <td>Chassis No</td><td>VR7EFYHCRMJ542597</td></tr> <tr> <td>Engine No</td><td>10Q4DR0030181</td></tr> <tr> <td>Make/Model</td><td>CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13</td></tr> <tr> <td>Colour/Trim</td><td>WPP / GY</td></tr> </table>	Cust No/Name	/Cycle & Carriage, Fulco Motor De	Reg No/Reg Date	GBL1784C / 30/03/2021	Date In/Mileage	17/01/2022/ 6319	Chassis No	VR7EFYHCRMJ542597	Engine No	10Q4DR0030181	Make/Model	CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13	Colour/Trim	WPP / GY
Cust No/Name	/Cycle & Carriage, Fulco Motor De														
Reg No/Reg Date	GBL1784C / 30/03/2021														
Date In/Mileage	17/01/2022/ 6319														
Chassis No	VR7EFYHCRMJ542597														
Engine No	10Q4DR0030181														
Make/Model	CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13														
Colour/Trim	WPP / GY														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000051	Credit	24/06/2022/ 09:38	OD	303 / Renemer	25421

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO REMOVE & REPLACE RADIATOR ASSY & FRONT SUPPORT PANEL TO REMOVE & RE-INSTALL AC CONDENSER AND TO TOP UP AC GAS & COOLANT				✓ 180.00
M JJM2313950 COOLANT	4.00	26.00	0.00	✓ 104.00
Z NOTES SUPPLEMENTARY ITEMS & LABOUR				

# Estimate

Confirm & accepted by	Parts	104.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	180.00
	Others(Lub,etc)	0.00
	Sundry	0.00
Authorized signatory and company stamp	Total(w/o GST)	284.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897  TEL: 67143369  Contact No	Cust No/Name /Cycle & Carriage.Fulco Motor De Reg No/Reg Date GBL1784C / 30/03/2021 Date In/Mileage 17/01/2022/ 6319 Chassis No VR7EFYHJRMJ542597 Engine No 10Q4DR0030181 Make/Model CITCV/K9 BERLINGO L2 1.5 BLUEHDI 13 Colour/Trim WPP / GY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000051	Credit	26/05/2022/ 09:39	OD	303 / Renemer	25421			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	C1610817780	LH STEERING ROD BALL	/	GP	1.00	195.00	0.00	195.00
X	C9677914480	LHF DRIVE SHAFT	/	GP	1.00	650.00	0.00	650.00
M	C9816824080	RH HEADLIGHT ASSEMBL	/	GP	1.00	620.00	0.00	620.00
M	C98029781XT	LH DOOR HANDLE	/	BR	1.00	67.00	0.00	67.00
M	C9822171580	LH DOOR ADHESIVE TAP	/	MC	1.00	10.00	0.00	10.00
M	C9818018380	LH W/STRIP DOOR ENTR	/	MC	1.00	207.00	0.00	207.00
M	C9675747980	RADIATOR ASSY	/	BR	1.00	545.00	0.00	545.00
M	C9830335880	LH WINDOW LIFTER ELE	/	CPA	1.00	492.00	0.00	492.00
Z	NOTES							
SUPPLEMENTARY ITEMS								

# Estimate

Estimate  
27/5/22

Confirm & accepted by	Parts	2,786.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	0.00
	Others(Lub,etc)	0.00
	Sundry	0.00
Authorized signatory and company stamp	Total(w/o GST)	2,786.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.