



Your Ref : HLBAISCL2022-00002

Date: 04th Mar 2022

Our Ref : CS4/AIS22001211/LNtf3e2

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01

Singapore 068897

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE PA 9341L
ACCIDENT ON 07/02/2022**

Instruction was received to inspect the vehicle Reg. No. PA 9341L. The inspection was conducted on 09/02/2022 at the premises of M/s Connect3, 7 Old Toh Tuck Road, Singapore 597648.

The following vehicle information was recorded:

Registration Number	: PA 9341L
Make/Model	: Higer KLQ6109Q 6.7L MT ABS Turbo
Year of Registration	: 2010
Body Colour	: Yellow
Chassis Number	: LKLR1FSJ79B528753
Engine Capacity	: 6692 cc
Speedometer Reading	: Not Available

The vehicle caught fire. The cause of fire probably due to short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 75,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 19,774.00)
Nett Liability	<u>S\$ 55,226.00</u> =====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MII(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.