

**Section A - Accident Details**

Registration Number	SHF339Y
Case Reference Number	TAX/02/22/2014
Registration Date	10/10/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	ANG BENG KEE
Type of Accident	Side Swipe
Accident Date and Time	6/2/2022 11:25 PM
Accident Reported Date and Time	7/2/2022 11:43 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113899
Special Instruction to ARC, if any	TP / TOWED \$40
Prepared Date and Time	7/2/2022 3:46 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$80.00
Total Spray Cost	\$1,314.00	\$50.00
Total Spare Part Cost	\$3,081.61	\$1,042.62
Total Other Cost	\$416.00	\$20.00
<b>TOTAL COST</b>	<b>\$5,318.61</b>	<b>\$1,192.62</b>
<b>Lump Sum Total</b>	<b>\$5,300.00</b>	<b>\$1,200.00 (L/S)</b>
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / Allianz Insurance
ARC / Surveyor Sign Off Date	09/02/2022 2:02 PM	09/02/2022 12:25 PM
Signature		
Remarks		L/S repair. take after spray

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2202-0236	<b>Invoice Number</b>	
<b>Quotation Date</b>	17.02.2022	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$507.00	\$80.00
<b>Total Labour</b>	<b>\$507.00</b>	<b>\$80.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
RESPRAY MIRROR COVER RH	\$180.00	\$50.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00
TO RESPRAY REAR DOOR RH	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,314.00</b>	<b>\$50.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$0.00
<b>Total Other Costs</b>	<b>\$416.00</b>	<b>\$20.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8791047450	MIRROR ASSY, OUTER REAR VIEW, RH	1.00	\$1,373.50	10.00	\$1,236.15	Replace	Replace
		8791547070A1	COVER, OUTER MIRROR, RH	1.00	\$89.50	25.00	\$67.13	Replace	Replace
		6700147152	PANEL SUB-ASSY, FRONT DOOR RH	0.00	\$1,249.60	0.00	\$0.00	Replace	Not Given
			STICKER DECAL STRIDES (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	0.00	\$1,243.90	0.00	\$0.00	Replace	Not Given
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given
<b>Total</b>					<b>\$4,841.30</b>		<b>\$1,303.28</b>		

√  
√  
X  
X  
X  
X

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

1,303.28  
 -20% L/S \$1,200/-  
 1042.62  
 80.00  
 70.00  
 1,192.62