

Case Details

Case Reference Number : TAX/02/22/2014
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF339Y

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-17405-ID
 Assigned By : Selena Tan Lee See

Insurance Company Name : Allianz Insurance Co of (S) Pte Ltd
 Accident Date and Time : 06/02/2022 03:25 PM
 Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks	
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW, RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	1	1,236.15	Replace	✓ BR	
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	1	67.13	Replace	✓ MIS	
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	0	0	Not Give	✓ X nn	
One Time Key In	Main			STICKER DECAL STRIDES (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	✓ X nn	
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	1,243.90	25.00	932.93	Replace	0	0	Not Give	✓ X nn	
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Give	✓ X nn	
Total Spare Part Cost									3,852.01	Surveyor Total		1,303.28			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20			
Final Spare Part Cost									3,081.61	Final Sur Total		1,042.62			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			507.00	80.00	

Main

Job Scope
TO REPAIR RH PORTION

SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
507.00	80	/
507.00	80.00	

Total:

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	RESPRAY MIRROR COVER RH	180.00	50	/
2	Main	TO RESPRAY FRONT DOOR RH	378.00	0	X
3	Main	TO RESPRAY REAR DOOR RH	378.00	0	X
4	Main	TO RESPRAY REAR FENDER RH	378.00	0	X
Total:			1,314.00	50.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	X m
2	Main	TO REPLACE SUNDRY PARTS	100.00	0	X m
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ nec
4	Main	TO WASH AND VACUUM	60.00	0	X m
5	Main	TOWING CHARGE	56.00	0	X m
Total:			416.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,081.61	1,042.62
Total Labour Cost	507.00	80.00
Total Spray Painting	1,314.00	50.00
Other	416.00	20.00
Overall Total	5,318.61	1,192.62
Lump Sum Repair Option		<input checked="" type="checkbox"/>

7078.30

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Sum Total	5,300.00	1,200.00
Surveyor Approved Amount		1,200.00
No of Repair Days*	5	2
Remarks		L/S repair, take after spray
Surveyor Name		STEVE CHEN
Signature		
		<input type="button" value="Save"/> <input type="button" value="Clear"/>

Survey Date

09/02/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Steve (LKK)
9/2/22, 12.00pm
With Prejudice
2 days
L/S