

ASS. REC. BY: Marcus

REF:

CC6/AG 2200 1214/U223

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Good~~ / Jammed / Leaked / Burnt or

Brake: ~~Good~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:


Transportation:

S + RS SI

Photos

Others

TOTAL



24/2/22 45 \$5150 informed willian

Not Authorised
du
9/2/22



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SMY8960R
Date of Accident : 08 February 2022

Ukph Sebaraky

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

5 days
2/5 # 5150

Messrs Goldtron Enterprise & Services Pte Ltd

Date : 08 February 2022

req: Ukh - Marcus

04/02/2022 09:30h

Estimate To Repair GBJ2571D - Toyota HIACE VAN TURBO 4DR AT
Chassis No : JTFHT02PX00247747

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>body</i>	\$ 1,979.70
02	1 pc	tailgate lid centre logo badge <i>new</i>	\$ 71.60
03	1 pc	tailgate lid lock top <i>02/20</i>	\$ 262.30
04	1 pc	tailgate lid lock latch bottom <i>11</i>	\$ 180.00
05	1 pc	tailgate lid weatherstrip <i>new</i>	\$ 189.60
06	2 ps	tailgate lid rubber stopper @ \$25.00 <i>11</i>	\$ 50.00
07	2 ps	tailgate lid side catch @ \$26.40 <i>11</i>	\$ 52.80
08	2 ps	tailgate lid side catch latch @ \$48.90 <i>11</i>	\$ 97.80
09	1 pc	rear end panel - outer <i>body</i>	\$ 388.30
10	1 pc	rear end panel - inner <i>body</i>	\$ 1,155.00
11	1 pc	rear windscreen weatherstrip <i>new</i>	\$ 298.70
12	1 pc	rear bumper <i>new</i>	\$ 395.00
13	1 pc	rear bumper beam <i>new</i>	\$ 165.00
14	4 ps	rear bumper side holder clips @ \$10.80 <i>11</i>	\$ 43.20
15	2 ps	rear bumper side holder @ \$25.50 <i>11</i>	\$ 51.00
16	2 ps	rear lamp @ \$360.00 <i>new side of 11</i>	\$ 720.00
17	6 ps	rear lamp holder clips @ \$5.00 <i>11</i>	\$ 30.00
18	2 ps	rear lamp panel @ \$135.00 <i>new</i>	\$ 270.00
19	1 pc	spare-tyre carriage holder <i>11</i>	\$ 485.60
20	2 ps	rear fender air vent @ \$235.00 <i>11</i>	\$ 470.00
21	2 ps	rear lamp corner panel @ \$45.00 <i>R</i>	\$ 90.00
Less 25 % <i>Rear steel plate \$240.10 sent</i>			\$ 7,445.60
			\$ 1,861.40
			\$ 5,584.20
<u>SPECIAL NETT ITEMS</u>			
22	1 pc	tailgate lid 70KM/H sticker <i>new</i>	\$ 20.00
23	1 pc	rear windscreen sealant <i>new</i>	\$ 60.00
24	1 pc	tailgate lid Hiace badge <i>new</i>	\$ 48.00
25	1 pc	tailgate lid Toyota badge <i>new</i>	\$ 72.00
26	1 set	rear bumper parking sensor <i>shorted</i>	\$ 450.00
	<i>vpc</i>	<i>Rear license plate one 40 s/n</i>	\$ 650.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 50.00
02		To rust-proofing of the affected areas.	\$ 150.00
03		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00
04		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 120.00

20
60
60
X



廣林摩呀利人有限公司
TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SMY8960R

Date of Accident : 08 February 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Goldtron Enterprise & Services Pte Ltd

Date : 08 February 2022

Estimate To Repair GBJ2571D - Toyota HIACE VAN TURBO 4DR AT
Chassis No : JTFHT02PX00247747

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
05		To remove and refit rear windscreen glass.	\$ 120.00 ✓
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,300.00 1000
07		Putty and spray painting of the affected portion.	\$ 950.00 850
			\$ 2,810.00
		Total	\$ 9,044.20

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5316.60
282
P- 3987.45
S-N- 360
L- 2110
6457.45
201
5165