

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	07 Feb 2022 13:38	Clm Veh Model Changed		[] Merimen Administrator
2	07 Feb 2022 13:38	Clm Created	Reg No: SDQ767J. Policy No: 1900251744-01. Acct Date: 2022/02/05. Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SA0122270007	[I] Merimen Administrator
3	09 Feb 2022 11:35	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	09 Feb 2022 11:35	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	09 Feb 2022 11:35	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	09 Feb 2022 11:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/02/18	[A] CELINE FONG
7	09 Feb 2022 11:35	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	09 Feb 2022 11:35	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	09 Feb 2022 11:35	Clm Veh Model Changed	(207156) AUDI A3 999cc SEDAN TFSI S TRONIC (LED) (A).	[A] CELINE FONG
10	09 Feb 2022 11:35	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
11	10 Feb 2022 10:29	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	10 Feb 2022 10:29	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	10 Feb 2022 10:29	Clm Dtl Modified	JPJ Reg. Date: -> 2019/11/25.	[A] Elaine Kuan Hwa Meen
14	10 Feb 2022 10:29	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	10 Feb 2022 13:41	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/02/18	[A] SHIAU CHAN
16	10 Feb 2022 13:42	Adj Mandate Request	Cur.Reg:21572.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN

AUDIT TRAIL				
No.	On	Audit	Remarks	By
17	10 Feb 2022 16:11	CIm Registration Modified	Init.Est.:->4,000 - 5,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Azlan, Syazairdina
18	10 Feb 2022 18:49	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/02/18. Mandate Remarks: Vehicle may commence repair - A/C condenser to take CLEAR photos for damage during dismantle. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency.	[I] Lim, Kok-Chong
19	10 Feb 2022 18:49	Adj Mandate Set	Approved:10254.00:Vehicle may commence repair - A/C condenser to take CLEAR photos for damage during dismantle. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Pa	[I] Lim, Kok-Chong
20	15 Feb 2022 14:46	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/02/18	[A] SHIAU CHAN
21	15 Feb 2022 14:47	Adj Mandate Request	Cur.Req:32865.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
22	15 Feb 2022 16:48	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/02/18. Mandate Remarks: Mechatronic, LH Headlamp, Engine Under Cover to take CLEAR photos for damage - refer Adrian Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency.	[I] Lim, Kok-Chong
23	15 Feb 2022 16:48	Adj Mandate Set	Approved:30605.00:Mechatronic, LH Headlamp, Engine Under Cover to take CLEAR photos for damage - refer Adrian Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Pan	[I] Lim, Kok-Chong

Date From		 	Date To		 	Audit Type	None	Go
------------------	----------------------	---	----------------	----------------------	---	-------------------	-----------------------------------	-----------------------------------

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2764571	10 Feb 2022 10:29:47	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDQ767J		11.00