




Supplementary Estimate-1

Xiao Chan.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0084/2022/JT 14-Feb-22 CHANG 1 of 1 SDQ 767 J AUDI A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO DISMANTLE AND RENEW GEARBOX MACHATRONIC UNIT AND CARRY OUT ADAPTATION.	\$ 980.00	✓
<u>Parts</u>			
1	MECHATRONIC WITH SOFTWARE <i>Dented</i>	\$ 4,426.00	✓
GRAND TOTAL		\$ 5,406.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Lj

14/02/22

HLG

Add 1 Day for replacement of mechatronic.

total Repair days = 7+1=8 Days
HLG

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDQ 767 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X.
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	X. + 250. S.S.
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACUUM AND REGAS.	S/N \$ 1,400.00	✓ S.S.
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1000 (without lock carrier) 2250 (with lock carrier) S.S.
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDERS.	\$ 4,000.00	1100
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192
TOTAL LABOUR CHARGES		\$ 11,044.00	

Car in

11/2/22.

wip: 10454

Kiam/choy



PREMIUM AUTOMOBILES

55 UBI ROAD #1, SINGAPORE 408699
TEL: 6386 2329 FAX: 6841 1163
EMAIL: NORAKHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 767 J


A2G-Hoham
- 4/7 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dehid</i>	1	\$ 1,987.00	✓
2	FRONT BUMPER FIXING PARTS <i>per m</i>	1	\$ 195.00	✓
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>per m</i>	2	\$ 86.00	+
4	FRONT BUMPER GRILLE - CENTER <i>cracked</i>	1	\$ 179.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>Dehid</i>	1	\$ 571.00	✓
6	FRONT BUMPER CLOSING ELEMENT - LH / RH ?	2	\$ 636.00	?
7	FRONT BUMPER TRIM COVER - LH / RH <i>per m</i>	2	\$ 364.00	+
8	FRONT BUMPER ADAPTER - LH / RH <i>per m</i>	2	\$ 84.00	+
9	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,406.00	✓
10	RADIATOR CLOSING ELEMENT <i>cracked</i>	1	\$ 210.00	✓
11	RADIATOR AIR GUIDE GRILLE LH / RH <i>per m</i>	2	\$ 420.00	210.00 ✓
12	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 211.00	✓
13	FRONT BUMPER REINFORCEMENT BEAM <i>Dehid</i>	1	\$ 847.00	✓
14	FRONT BUMPER REINFORCEMENT BEAM COVER <i>cracked</i>	1	\$ 136.00	✓
15	AIR COND STICKER ?	1	\$ 9.00	✓
16	CAUTION STICKER <i>Nec</i>	1	\$ 16.00	✓
17	HORN - LH / RH <i>per m</i>	2	\$ 426.00	+
18	FRONT WHEEL HOUSING LINER - LH / RH <i>per m</i>	2	\$ 366.00	+
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>per m</i>	1	\$ 93.00	+
20	BONNET <i>Dented</i>	1	\$ 3,134.00	✓
SUB TOTAL SPARE PARTS		:	\$ 11,376.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6396 2323 FAX : 6841 1183
 EMAIL: NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 767 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET ATTACHMENT PARTS <i>Not in</i>	1	\$ 172.00	X
22	BONNET HINGE - LH / RH	2	\$ 136.00	X
23	BONNET CATCH HOOK	1	\$ 100.00	X
24	BONNET STRIKER - LH / RH	2	\$ 246.00	X
25	BONNET EDGE PROTECTION <i>Not in</i>	1	\$ 31.00	✓
26	BONNET MICRO-SWITCH <i>Not in</i>	2	\$ 455.00	X
27	BONNET CATCH HOOK - LOWER	1	\$ 71.00	X
28	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	X
29	BONNET RELEASE CABLE COVER	1	\$ 11.00	X
30	BONNET LOCK CABLE	1	\$ 82.00	X
31	BONNET SOUND ABSORBER	1	\$ 244.00	X
32	PLENUM CHAMBER	1	\$ 199.00	X
33	HEADLIGHT (LH / RH) <i>LH chipped</i>	2	\$ 10,910.00	X <i>3755 S/S</i>
34	LIFT CYLINDER - LH / RH	2	\$ 312.00	X
35	LIFT CYLINDER HOSE	1	\$ 78.00	X
36	WASH WATER RESERVOIR	1	\$ 225.00	X
37	LOCK CARRIER <i>Cracked</i>	1	\$ 805.00	✓ <i>S/S</i>
38	A/C CONDENSER <i>Dented</i>	1	\$ 569.00	✓
39	REFRIGERANT LINE ?	1	\$ 499.00	?
40	REFRIGERANT LINE ?	1	\$ 569.00	?
SUB TOTAL SPARE PARTS		:	\$ 15,779.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6386 2323 FAX : 6841 1183
 EMAIL: HORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 767 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 21.00	?
42	ADDITIONAL RADIATOR <i>Dented</i>	1	\$ 959.00	✓ <i>H.S.</i>
43	ADDITIONAL RADIATOR BRACKET - UPPER ?	2	\$ 90.00	?
44	RADIATOR BUSH - LOWER ?	2	\$ 22.00	?
45	RADIATOR <i>Dented</i>	1	\$ 1,061.00	✓ <i>H.S.</i>
46	RADIATOR COOLANT <i>over</i>	6	\$ 282.00	✓ <i>H.S.</i>
47	RADIATOR FAN RING <i>crushed</i>	1	\$ 1,464.00	✓ <i>H.S.</i>
48	RADIATOR AIR GUIDE (LH) RH <i>not crushed</i>	2	\$ 58.00	✓ <i>28</i>
49	RADIATOR SEAL - RH OUTER ?	1	\$ 9.00	?
50	RADIATOR AIR GUIDE - UPPER CENTER ?	1	\$ 14.00	?
51	NOISE INSULATION <i>crushed</i>	1	\$ 376.00	✓ <i>H.S.</i>
52	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓
53	SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 31,969.00	
TOTAL LABOUR CHARGES		:	\$ 11,044.00	
GRAND TOTAL		:	\$ 43,013.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.