

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg




Supplementary Estimate-1

Xiao Chan.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0084/2022/JT 14-Feb-22 CHANG 1 of 1 SDQ 767 J AUDI A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO DISMANTLE AND RENEW GEARBOX MACHATRONIC UNIT AND CARRY OUT ADAPTATION.	S/N \$ 980.00	✓✓
<u>Parts</u>			
1	MECHATRONIC WITH SOFTWARE <i>Dented</i>	\$ 4,426.00	✓ 3540.80
GRAND TOTAL		\$ 5,406.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Lj

14/02/22

HLG

Add 1 Day for replacement
of mechatronic.

total Repair days = 7+1=8 Days
HLG

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDQ 767 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X. ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	X. + 250. ✓ S.S.
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACUUM AND REGAS.	S/N \$ 1,400.00	✓ ✓ S.S.
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2250 4,298.00	1000 (without lock carrier) 2250 (with lock carrier) S.S.
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDERS.	\$ 4,000.00	1100 ✓
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192 ✓
TOTAL LABOUR CHARGES		: \$ 11,044.00	

Car in 11/2/22.

wip: 10454

Kiam/choy



PREMIUM AUTOMOBILES

55 UBI ROAD #1, SINGAPORE 408699
TEL: 6386 2329 FAX: 6841 1163
EMAIL: NORAKHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

A2G-Hoham
- 4/7 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 767 J


DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dehid</i>	1	\$ 1,987.00	✓ 1589.60
2	FRONT BUMPER FIXING PARTS <i>seen</i>	1	\$ 195.00	✓
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>seen</i>	2	\$ 86.00	✓
4	FRONT BUMPER GRILLE - CENTER <i>cracked</i>	1	\$ 179.00	✓ 143.20
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>Dehid</i>	1	\$ 571.00	✓ 456.80
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>? NN</i>	2	\$ 636.00	? X
7	FRONT BUMPER TRIM COVER - LH / RH <i>seen</i>	2	\$ 364.00	✓
8	FRONT BUMPER ADAPTER - LH / RH <i>seen</i>	2	\$ 84.00	✓
9	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,406.00	✓ 1124.80
10	RADIATOR CLOSING ELEMENT <i>cracked</i>	1	\$ 210.00	✓ 168
11	RADIATOR AIR GUIDE GRILLE LH / RH <i>seen</i>	2	\$ 420.00	✓ 210
12	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 211.00	✓ 168.80
13	FRONT BUMPER REINFORCEMENT BEAM <i>Dehid</i>	1	\$ 847.00	✓ 677.20
14	FRONT BUMPER REINFORCEMENT BEAM COVER <i>cracked</i>	1	\$ 136.00	✓ 108.80
15	AIR COND STICKER <i>? Nec</i>	1	\$ 9.00	✓ 6.64
16	CAUTION STICKER	1	\$ 16.00	✓ 12.40
17	HORN - LH / RH <i>seen</i>	2	\$ 426.00	✓
18	FRONT WHEEL HOUSING LINER - LH / RH <i>seen</i>	2	\$ 366.00	✓
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>seen</i>	1	\$ 93.00	✓
20	BONNET <i>Dented</i>	1	\$ 3,134.00	✓ 2507.20
SUB TOTAL SPARE PARTS		:	\$ 11,376.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

168
168

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6396 2323 FAX: 6841 1183
 EMAIL: NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 767 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET ATTACHMENT PARTS <i>Not</i>	1	\$ 172.00	X
22	BONNET HINGE - LH / RH	2	\$ 136.00	X
23	BONNET CATCH HOOK	1	\$ 100.00	X
24	BONNET STRIKER - LH / RH	2	\$ 246.00	X
25	BONNET EDGE PROTECTION <i>Not</i>	1	\$ 31.00	✓ 24.72
26	BONNET MICRO-SWITCH <i>Not</i>	2	\$ 455.00	X
27	BONNET CATCH HOOK - LOWER	1	\$ 71.00	X
28	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	X
29	BONNET RELEASE CABLE COVER	1	\$ 11.00	X
30	BONNET LOCK CABLE	1	\$ 82.00	X
31	BONNET SOUND ABSORBER	1	\$ 244.00	X
32	PLENUM CHAMBER	1	\$ 199.00	X
33	HEADLIGHT (LH / RH) <i>LH chipped</i>	2	\$ 10,910.00	X <i>3755</i> <i>sls</i> 4364
34	LIFT CYLINDER - LH / RH	2	\$ 312.00	X
35	LIFT CYLINDER HOSE	1	\$ 78.00	X
36	WASH WATER RESERVOIR	1	\$ 225.00	X
37	LOCK CARRIER <i>Not</i>	1	\$ 805.00	X
38	A/C CONDENSER <i>Not</i>	1	\$ 569.00	✓ 454.80
39	REFRIGERANT LINE ? NN	1	\$ 499.00	?
40	REFRIGERANT LINE ? NN	1	\$ 569.00	?
SUB TOTAL SPARE PARTS			\$ 15,779.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6386 2323 FAX : 6841 1183
 EMAIL: HORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 767 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	OUTSIDE TEMPERATURE SENSOR BRACKET ? NN	1	\$ 21.00	? X
42	ADDITIONAL RADIATOR <i>Dented</i>	1	\$ 959.00	? X <i>HL's</i> 766.80
43	ADDITIONAL RADIATOR BRACKET - UPPER ? NN	2	\$ 90.00	? X
44	RADIATOR BUSH - LOWER ? NN	2	\$ 22.00	? X
45	RADIATOR <i>Dented</i>	1	\$ 1,061.00	? X <i>HL's</i> 848.80
46	RADIATOR COOLANT <i>over</i>	6	\$ 282.00	? X <i>HL's</i> 225.60
47	RADIATOR FAN RING <i>crushed</i>	1	\$ 1,464.00	? X <i>HL's</i> 1171.20
48	RADIATOR AIR GUIDE (LH) RH <i>not crushed</i>	2	\$ 56.00	? X <i>HL's</i> 22.16
49	RADIATOR SEAL - RH OUTER ? NN	1	\$ 9.00	? X
50	RADIATOR AIR GUIDE - UPPER CENTER ? NN	1	\$ 14.00	? X <i>HL's</i> 300.80
51	NOISE INSULATION <i>crushed</i>	1	\$ 376.00	? X
52	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	? 60
53	SUNDRIES ? nec		\$ 400.00	? 18 ✓
TOTAL SPARE PARTS			\$ 31,969.00	
TOTAL LABOUR CHARGES			\$ 11,044.00	
GRAND TOTAL			\$ 43,013.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Xiao Chen.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0084/2022/JT

14-Apr-22

GLORY

1 of 1

SDQ 767 J

AUDI A3 SEDAN 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>PARTS</u> <u>1</u>	TRANSMISSION OIL <i>Ner</i>	\$ 142.00	<i>✓</i> 112.96
GRAND TOTAL		\$ 142.00	

For Premium Automobiles Pte Ltd

Adrian Ling
H.S.

Authorised Signature