

55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0084/2022/JT
DATE : 7-Feb-22
WIP : 10454

Xiao Chan.

\$26218.88.

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR STEPHEN LEUNG KIN WAH
ADDRESS : BLK 6 HOLLAND CLOSE
#15-22
SINGAPORE 271006
TELEPHONE : HP +65 81680022
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900251744-01
VEHICLE NO : SDQ 767 J
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 25/11/2019
ENGINE NO : CHZ C31091
CH/SSIS NO : WAUZZZ8V1KA096488
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Feb-22
PLACE OF ACCIDENT : UPPER PAYA LEBAR ROAD

PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDQ 767 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS. OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	S/N \$ 360.00	✓ H.S.
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$ 700.00 X 250	H.S.
3	TO REMOVE AN RENEW AIRCON CONDENSER ADDITIONAL RADIATOR AND RADIATOR CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM VACUUM AND REGAS.	S/N \$ 1400.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER BONNET AND BOTH HEADLIGHTS TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4200.00	1000 (without lock carrier) <u>2250</u> (With lock carrier) H.S.
5	TO RESPRAY FRONT BUMPER BONNET HINGES AND BOTH FRONT FENDERS.	\$ 4000.00	1100
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 364.00	192
TOTAL LABOUR CHARGES		: \$ 11,044.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 767 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dented</i>	1	\$ 1,987.00	✓
2	FRONT BUMPER FIXING PARTS <i>per m</i>	1	\$ 195.00	✓
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>per m</i>	2	\$ 86.00	+
4	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	1	\$ 179.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>Dented</i>	1	\$ 571.00	✓
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>Not Rec</i>	2	\$ 636.00	✗
7	FRONT BUMPER TRIM COVER - LH / RH <i>per m</i>	2	\$ 364.00	+
8	FRONT BUMPER ADAPTER - LH / RH <i>per m</i>	2	\$ 84.00	+
9	RADIATOR GRILLE <i>crushed</i>	1	\$ 1,406.00	✓
10	RADIATOR CLOSING ELEMENT <i>crushed</i>	1	\$ 210.00	✓
11	RADIATOR AIR GUIDE GRILLE - LH / RH <i>Not Rec</i>	2	\$ 420.00	✗ 210.
12	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	1	\$ 211.00	✓
13	FRONT BUMPER REINFORCEMENT BEAM <i>Dented</i>	1	\$ 847.00	✓
14	FRONT BUMPER REINFORCEMENT BEAM COVER <i>crushed</i>	1	\$ 136.00	✓
15	AIR COND STICKER <i>Not Rec</i>	1	\$ 9.00	✓
16	CAUTION STICKER	1	\$ 16.00	✓
17	HORN - LH / RH <i>per m</i>	2	\$ 426.00	+
18	FRONT WHEEL HOUSING LINER - LH / RH <i>per m</i>	2	\$ 366.00	+
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>per m</i>	1	\$ 93.00	+
20	BONNET <i>Dented</i>	1	\$ 3,134.00	✓
SUB TOTAL SPARE PARTS			\$ 11,376.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1 SINGAPORE 408699
TEL 6766 2323 FAX 6841 1183
EMAIL: NORA.KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 767 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 172.00	X
22	BONNET HINGE - LH / RH <i>2</i>	2	\$ 136.00	X
23	BONNET CATCH HOOK <i>new</i>	1	\$ 100.00	X
24	BONNET STRIKER - LH / RH	2	\$ 246.00	X
25	BONNET EDGE PROTECTION <i>new</i>	1	\$ 31.00	✓
26	BONNET MICRO-SWITCH <i>new</i>	2	\$ 455.00	X
27	BONNET CATCH HOOK - LOWER	1	\$ 71.00	X
28	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	X
29	BONNET RELEASE CABLE COVER	1	\$ 11.00	X
30	BONNET LOCK CABLE	1	\$ 82.00	X
31	BONNET SOUND ABSORBER	1	\$ 244.00	✓
32	PLENUM CHAMBER	1	\$ 199.00	X
33	HEADLIGHT - LH / RH	2	\$ 545.00 <i>545.5</i>	X
34	LIFT CYLINDER - LH / RH	2	\$ 312.00	X
35	LIFT CYLINDER HOSE	1	\$ 78.00	X
36	WASH WATER RESERVOIR	1	\$ 225.00	X
37	LOCK CARRIER <i>cracked</i>	1	\$ 806.00	✓
38	A/C CONDENSER <i>Denied</i>	1	\$ 569.00	✓
39	REFRIGERANT LINE <i>new</i>	1	\$ 499.00	X
40	REFRIGERANT LINE <i>new</i>	1	\$ 569.00	X
SUB TOTAL SPARE PARTS			\$ 15,779.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 767 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Not new</i>	1 S	21.00	X
42	ADDITIONAL RADIATOR <i>Dented.</i>	1 S	959.00	✓
43	ADDITIONAL RADIATOR BRACKET - UPPER <i>Not new</i>	2 S	90.00	X
44	RADIATOR BUSH - LOWER <i>Not new</i>	2 S	22.00	X
45	RADIATOR <i>Dented.</i>	1 S	1061.00	✓
46	RADIATOR COOLANT <i>New</i>	6 S	282.00	✓
47	RADIATOR FAN RING <i>crushed.</i>	1 S	1464.00	✓
48	RADIATOR AIR GUIDE - LH / RH <i>2H crushed</i>	2 S	56.00	28. ✓
49	RADIATOR SEAL - RH OUTER <i>Not new</i>	1 S	9.00	X
50	RADIATOR AIR GUIDE - UPPER CENTER <i>Not new</i>	1 S	14.00	X
51	NOISE INSULATION <i>crushed.</i>	1 S	376.00	✓
52	FRONT NO PLATE <i>Dented</i>	S/N S	60.00	✓
53	SUNDRIES <i>New</i>	S	400.00	78. ✓
TOTAL SPARE PARTS		:	\$	31,969.00
TOTAL LABOUR CHARGES		:	\$	11,044.00
GRAND TOTAL		:	\$	43,013.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6766 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Adrian Lim.
: 08/02/22 ✓

:
: 4 Days (Without lock carrier)
: Not Authorised, 7 Days (With lock carrier)
:

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
: THE AFFECTED VEHICLE. SHOULD WE REQUIRE
: FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
: PROGRESS OF REPAIR, WE SHALL INFORM YOU
: ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL. 6768 9828 / 6768 9911 FOR
APPOINTMENT.

08 Days.

fl/s

YOURS FAITHFULLY

PREMIUM AUTOMOBILES PTE LTD

Please inform
Premium.

10 Days. fl/s.
Cannot fl/s.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT