

TOTAL

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBD314A220128

Estimate

Customer

Name: India International Insurance Pte Ltd

Date: 08-02-22

Address: Motor Claims Department

Vehicle No: GBD314A

64 Cecil Street #04-00 & #05-00

Model/Make: Fiat Doblo Cargo

IOB Building Singapore 049711

SX JTD 1.6 MJ Panel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>DD 589.00</i>	\$ 627.00	☒
2	Bumper Clips 1 set <i>nel 50.00</i>	\$ 65.00	☒
3	Bumper Reinforcement <i>DD 461.00</i>	\$ 475.30	☒
4	Bumper Reverse Sensor 1 set <i>shotel 102</i>	\$ 220.00	SN 200 S/N
5	Tailgate "70 KM/H" Sticker <i>nel</i>	\$ 12.00	SN 10 S/N
6	Tailgate "6 PAX" Sticker <i>nel</i>	\$ 12.00	SN 10 S/N
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	400
	To putty & spray painting & including touch up paint on accident affected	\$ 600.00	550

Total Parts & Labour of estimate for damaged vehicle

\$ 2,511.30

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

** see file*

Not Authored
lll
9/2/22
f/s \$ 1700
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1100
102
1-990
S.N-220
L-950
2160