



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SR AUTOWORKS PTE LTD
BLK 8, KAKI BUKIT AVENUE 4,
#02-24 PREMIER @ KAKI BUKIT
SINGAPORE 415875
ON BEHALF OF CHEONG CHOON LING

Ref: CS/TP22001229/Aqy3e2
Date: 04/05/2022
Code: TP544

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SFM 8797S
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	09/02/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTDKN36U301117068	Colour	WHITE
Odometer	395808 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FIRENZA	6 mm
L/H Front Tyre	195/65 R15	FIRENZA	6 mm
R/H Rear Tyre	195/65 R15	FIRENZA	6 mm
L/H Rear Tyre	195/65 R15	FIRENZA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/01/2022	Inspection Date	09/02/2022
Survey held at	SR AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**