

31	TAILGATE EMBLEM(HYBRID) As is New	1	\$ 82.90	\$ 82.90	✓
32	TAILGATE OUTER GRANISH	1	\$ 889.70	\$ 889.70	+
33	TAILGATE SIDE STOPPER(OUTER) } NP	2	\$ 55.00	\$ 110.00	+
34	TAILGATE SIDE STOPPER(INNER) } New	2	\$ 50.00	\$ 100.00	+
35	TAILGATE INNER LOCK As is New	1	\$ 457.90	\$ 457.90	+
36	TAILGATE WEATHERSTRIP New	1	\$ 365.20	\$ 365.20	+
37	TAILGATE INNER LOWER TRIM BOARD New	1	\$ 524.00	\$ 524.00	+
38	TAILGATE DETECTOR SENSOR As is New	1	\$ 482.40	\$ 482.40	✓ 135
39	TAILGATE HINGE } NP	2	\$ 89.00	\$ 178.00	+
40	TAILGATE ABSORBER } New	2	\$ 277.00	\$ 554.00	+
41	TAILLAMP LH As is New	2	\$ 1,115.80	\$ 2,231.60	7115.80
42	TAILLAMP SIDE COVER LH New	2	\$ 256.00	\$ 512.00	+
43	REAR BUMPER As is New	1	\$ 658.00	\$ 658.00	+
44	REAR LOWER BUMPER As is New	1	\$ 552.60	\$ 552.60	345
45	REAR BUMPER SIDE RETAINER New	1	\$ 120.00	\$ 120.00	✓
46	REAR BUMPER REINFORCEMENT As is New	1	\$ 318.40	\$ 318.40	✓
47	REAR BUMPER TOWING COVER Not New	1	\$ 66.00	\$ 66.00	+
48	REAR BUMPER LOWER SIDE GARNISH LH As is New	2	\$ 377.00	\$ 754.00	7377
49	REAR BUMPER UNDER COVER CENTER As is New	1	\$ 258.00	\$ 258.00	+
50	REAR BUMPER UNDER COVER SIDE As is New	2	\$ 254.00	\$ 508.00	+
51	REAR WIRE HARNESS As is New	1	\$ 653.70	\$ 653.70	+
52	END PANEL As is New	1	\$ 611.80	\$ 611.80	✓
53	END PANEL TOP GARNISH As is New	1	\$ 175.90	\$ 175.90	✓
54	REAR FLOOR PANEL As is New	1	\$ 845.00	\$ 845.00	+
55	REAR FLOOR PANEL TOP BOARD } NP	1	\$ 685.00	\$ 685.00	+
56	REAR FLOOR PANEL TOOL BOX } New	2	\$ 564.30	\$ 1,128.60	+
57	REAR FENDER INNER TRIM	2	\$ 655.70	\$ 1,311.40	+
58	REAR FENDER INNER SHIELD } Not New	2	\$ 225.00	\$ 450.00	+
59	REAR EXHAUST SILENSER } New	1	\$ 1,163.40	\$ 1,163.40	+
60	REAR EXHAUST MOUNTING	2	\$ 49.70	\$ 99.40	+
61	REAR EXHAUST GASKET	1	\$ 56.00	\$ 56.00	+
62	REAR EXHAUST HEATE PLATE	1	\$ 314.60	\$ 314.60	+

7022
\$266.50

Subtotal :	\$	33,433.20
Less 25% :	\$	8,358.30
Parts Total :	\$	25,074.90

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	FRONT NUMBER PLATE <i>Dented</i>	1	\$ 50.00	\$ 50.00	✓
2	FRONT BUMPER CLIPS <i>nec</i>	1	\$ 50.00	\$ 50.00	→ 30
3	COOLANT <i>nec nec</i>	1	\$ 80.00	\$ 80.00	+
1	TAILGATE CENTER MOULDING CLIP <i>nec nec</i>	1	\$ 50.00	\$ 50.00	+
2	TAILGATE INNER BOARD CLIP <i>nec nec</i>	1	\$ 50.00	\$ 50.00	+
3	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	+
4	TAILGATE WINDSCREEN INNER SEAL	1	\$ 50.00	\$ 50.00	+
5	TAILGATE QUARTER GLASS INNER SEAL	1	\$ 80.00	\$ 80.00	+
6	TAILGATE QUARTER GLASS SEALNAT	1	\$ 60.00	\$ 60.00	+
7	REAR BUMPER CLIP <i>nec</i>	1	\$ 60.00	\$ 60.00	30
8	REVERSE SENSOR <i>Damp</i>	1	\$ 380.00	\$ 380.00	2w
9	TAIL LAMP CLIP <i>? nec</i>	1	\$ 30.00	\$ 30.00	70
10	REAR END PANEL SEALANT <i>? nec</i>	1	\$ 80.00	\$ 80.00	?60
11	REAR FLOOR PANEL SEALANT <i>nec nec</i>	1	\$ 80.00	\$ 80.00	+
12	REAR FENDER INNER TRIM CLIP <i>? nec</i>	1	\$ 60.00	\$ 60.00	+
13	REAR FENDER INNER SHIELD CLIP <i>nec</i>	1	\$ 50.00	\$ 50.00	+
				SPECIAL NETT	\$ 1,290.00

380

LABOUR (FRONT)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00 300
TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00 250
TUFF COAT	\$ 250.00 +
WIRING AND BULB CHECK	\$ 50.00 30
REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$ 200.00 +
REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 200.00 +
LABOUR (REAR)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00 600
TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00 700
WIRING AND BULB CHECK	\$ 50.00 30
REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00 +
REMOVE AND REFIX TAILGATE QUARTER GLASS	\$ 150.00 +
TRANSFER TAILGATE MECHAISM	\$ 150.00 +
CONDUCT WATER LEAKAGE TEST	\$ 100.00 +
REMOVE AND REFIT REAR RACK TO FACILIAATE REPAIR	\$ 300.00 +
REMOVE AND REFIX TRIM, FLOOR MAT AND INTERIOR	\$ 350.00 600 +
REMOVE AND REFIX REAR REVERSE SENSOR	\$ 120.00 50
REMOVE AND REFIX REAR EXHAUST SYSTEM	\$ 300.00 +
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00 80
LABOUR TOTAL	
	\$ 8,820.00

	Total Parts Cost	\$ 26,364.90
	Total Labour Cost	\$ 8,820.00
	Total Repair Cost	\$ 35,184.90

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian Lij
 2/5 09/02/22.
 08 Days.
 Total: 7666.50
 2/5: 6.1K.