

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001230/KPA3Q2**Date:** 07/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700032286
Claimant Vehicle No :	SMX9849D	Insured Vehicle No :	SCQ1911P
Date of Loss:	03/02/2022	Nature of Claim:	TP
		Claim No:	3586669416SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX9849D	Engine No:	1NZR797380
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 X CVT (A)	Chassis No:	NHP1707177070
Reg. Date:	08/02/2021 (Man. Year: 2019)	Odometer:	76129 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	INTERTRAC 7 mm	Rear Left Side:	Toyo 2 mm
Front Right Side:	INTERTRAC 7 mm	Rear Right Side:	Toyo 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,225.50	3,035.17	6,190.33	67.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	2,030.00	1,140.00	35.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,395.50	5,065.17	7,330.33	59.14
Approved Total (Overridden) (S\$)		4,050.00		
(S\$)	12,395.50	4,050.00	8,345.50	67.33
+ GST 7.00/7.00% (S\$)	867.69	283.50	584.19	67.33
Nett Amount (S\$)	13,263.19	4,333.50	8,929.69	67.33
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
(S\$)		4,693.50		
Liabe Amount (50.00%) (S\$)		2,346.75		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,348.75		
Global Sum Settlement (S\$)		2,300.00		

INSPECTION

Date of Assignment:	09/02/2022	
Date Inspected:	09/02/2022	Inspected At: Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	49.20 FL	*- FL
2	1		*FRONT FENDER RH	Bent	579.20 FL	*579.20 FL
3	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	48.60 FL	*48.60 FL
4	1		*FRONT FENDER INNER SHIELD RH	Serviceable	175.60 FL	*- FL
5	1		*FRONT STEEL RIM RH	Repair	397.80 FL	*- FL
6	1		*FRONT SUSPENSION SHOCK ABSORBER RH	Serviceable	498.20 FL	*- FL
7	1		*FRONT SUSPENSION KNUCKLE ARM RH	Serviceable	558.90 FL	*- FL
8	1		*FRONT SUSPENSION WHEEL BEARING RH	Not Necessary	168.20 FL	*- FL
9	1		*FRONT SUSPENSION LOWER ARM RH	Serviceable	488.80 FL	*- FL
10	1		*FRONT DOOR RH	Bent	1,184.70 FL	*1,184.70 FL
11	1		*FRONT DOOR CHECKER RH	Serviceable	210.30 FL	*- FL
12	1		*FRONT DOOR HINGE UPPER RH	Repair	95.10 FL	*- FL
13	1		*FRONT DOOR HINGE LOWER RH	Repair	95.10 FL	*- FL
14	1		*FRONT DOOR WEATHERSTRIP RH	Serviceable	175.50 FL	*- FL
15	1		*FRONT DOOR INNER TRIM BOARD RH	Serviceable	1,211.20 FL	*- FL
16	1		*FRONT DOOR REGULATOR RH	Serviceable	237.10 FL	*- FL
17	1		*FRONT DOOR REGULATOR MOTOR RH	Damaged	747.50 FL	*747.50 FL
18	1		*FRONT DOOR MECHANISM LOCK RH	Repair	603.80 FL	*- FL
19	1		*FRONT DOOR LOCK STRIKER RH	Repair	40.70 FL	*- FL
20	1		*REAR SLIDING DOOR RH	Bent	1,281.10 FL	*1,281.10 FL
21	1		*REAR SLIDING DOOR LOWER GARNISH RH	Cut	135.40 FL	*135.40 FL
22	1		*REAR SLIDING DOOR MECHANISM LOCK RH	Repair	1,160.50 FL	*- FL
23	1		*REAR SLIDING DOOR LOCK STRIKER RH	Repair	60.10 FL	*- FL
24	1		*REAR FENDER RH	Repair	1,500.10 FL	*- FL
25	1		*REAR FENDER LOWER GARNISH RH	Cut	70.40 FL	*70.40 FL
26	1		*REAR FENDER INNER SHIELD RH	Serviceable	60.90 FL	*- FL
27	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*FRONT FENDER INNER SHIELD CLIPS RH	Not Necessary	30.00 FS	*- FS
29	1		*FRONT TYRE RH- 185/60 R15	Serviceable	180.00 FS	*- FS
30	1		*FRONT DOOR INNER TRIM BOARD CLIPS RH	Not Necessary	30.00 FS	*- FS
31	1		*REAR DOOR INNER TRIM BOARD CLIPS RH	Not Necessary	30.00 FS	*- FS
32	1		*REAR FENDER INNER SHIELD CLIPS RH	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,184.00	4,046.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,958.50	1,011.73
Total Parts (\$\$)	9,225.50	3,035.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST RIGHT ACCIDENT AREAS & ETC	New	1,200.00	700.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC	New	1,200.00	1,000.00
3	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	90.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC TO EFFECT REPLACE OF FRONT DOOR RH & REAR DOOR RH	New	240.00	120.00
5	TO REMOVE & REFIX FRONT WHEEL SUSPENSION ARM & ETC TO EFFECT ON FRONT FENDER RH	New	150.00	0.00
6	TO WHEEL ALIGNMENT & BALANCING	New	100.00	0.00
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	100.00	100.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (\$\$)			3,170.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >