

Date: 04/02/2022
Vehicle No: SMX9849D
Model: TOYOTA SIENTA HYBRID
Chassis: NHP1707177070
Reg.Year: 2019

Not Withheld
Survey B4 palm
6 days

Third Party Insurer: AIG
Third Party Veh No: SCQ1911P
Date of Accident: 03/02/2022
Estimator: KIT
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER SIDE RETAINER RH	1		<i>Pr</i> \$49.20	X
2	FRONT FENDER RH	1		<i>Pr</i> \$579.20	✓
3	FRONT FENDER "HYBRID" EMBLEM RH	1		<i>Pr</i> \$48.60	✓
4	FRONT FENDER INNER SHIELD RH	1		<i>Pr</i> \$175.60	X
5	FRONT STEEL RIM RH	1		<i>Pr</i> \$397.80	X
6	FRONT SUSPENSION SHOCK ABSORBER RH	1		<i>Pr</i> \$498.20	X
7	FRONT SUSPENSION KNUCKLE ARM RH	1		<i>Pr</i> \$558.90	X
8	FRONT SUSPENSION WHEEL BEARING RH	1		<i>Pr</i> \$168.20	X
9	FRONT SUSPENSION LOWER ARM RH	1		<i>Pr</i> \$488.80	X
10	FRONT DOOR RH	1		<i>Pr</i> \$1,184.70	✓
11	FRONT DOOR CHECKER RH	1		<i>Pr</i> \$210.30	X
12	FRONT DOOR HINGE UPPER RH	1		<i>Pr</i> \$95.10	X
13	FRONT DOOR HINGE LOWER RH	1		<i>Pr</i> \$95.10	X
14	FRONT DOOR WEATHERSTRIP RH	1		<i>Pr</i> \$175.50	X
15	FRONT DOOR INNER TRIM BOARD RH	1		<i>Pr</i> \$1,211.20	X
16	FRONT DOOR REGULATOR RH	1		SVC \$237.10	X
17	FRONT DOOR REGULATOR MOTOR RH	1		DAM \$747.50	✓
18	FRONT DOOR MECHANISM LOCK RH	1		<i>Pr</i> \$603.80	X
19	FRONT DOOR LOCK STRIKER RH	1		<i>Pr</i> \$40.70	X
20	REAR SLIDING DOOR RH	1		<i>Pr</i> \$1,281.10	✓
21	REAR SLIDING DOOR LOWER GARNISH RH	1		<i>Pr</i> \$135.40	✓
22	REAR SLIDING DOOR MECHANISM LOCK RH	1		<i>Pr</i> \$1,160.50	X
23	REAR SLIDING DOOR LOCK STRIKER RH	1		<i>Pr</i> \$60.10	X
24	REAR FENDER RH	1		<i>Pr</i> \$1,500.10	X
25	REAR FENDER LOWER GARNISH RH	1		<i>Pr</i> \$70.40	✓
26	REAR FENDER INNER SHIELD RH	1		<i>Pr</i> \$60.90	X
SUB TOTAL				\$11,834.00	
LESS 25%				-\$2,958.50	
PARTS TOTAL				\$8,875.50	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER CLIPS	1		<i>Pr</i> \$50.00	X
2	FRONT FENDER INNER SHIELD CLIPS RH	1		<i>Pr</i> \$30.00	X
3	FRONT TYRE RH - 185/60R15	1		<i>Pr</i> \$180.00	X
4	FRONT DOOR INNER TRIM BOARD CLIPS RH	1		<i>Pr</i> \$30.00	X

Head office

8 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6491 1922 | Fax: (+65) 6481 1011



Date: 04/02/2022
 Vehicle No: SMX9849D
 Model: TOYOTA SIENTA HYBRID
 Chassis: NHP1707177070
 Reg.Year: 2019

Third Party Insurer: AIG
 Third Party Veh No: SCQ1911P
 Date of Accident: 03/02/2022
 Estimator: KIT
 Surveyor:

5	REAR DOOR INNER TRIM BOARD CLIPS RH	1	~ \$30.00
6	REAR FENDER INNER SHIELD CLIPS RH	1	~ \$30.00
S/N TOTAL			\$350.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST RIGHT ACCIDENT AREAS & ETC.

\$1,200.00 *700*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.

\$1,200.00 *1000*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$100.00 *80*

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH & REAR DOOR RH

\$240.00 *120*

TO REMOVE & REFIX FRONT WHEEL SUSPENSION ARM & ETC. TO EFFECT ON FRONT FENDER RH

~ \$150.00 *X*

TO WHEEL ALIGNMENT & BALANCING.

~ \$100.00 *X*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$100.00 *✓*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 *20*

LABOUR TOTAL \$3,170.00

KIT TOTAL \$12,395.50

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 6 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

