OPTIMAMERKZ SINGAPORE

TOYOTA SIENTA HYBRID

NHP1707177070

OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sg

(i) /OptimaWerkz

/optimaWerkz

Date:

Model:

04/02/2022

Vehicle No: SMX9849D

Not Norhara

Third Party Insurer:

Third Party Veh No:

Date of Accident:

Estimator:

AIG

SCQ1911P

03/02/2022

KIT

Chassis: Reg.Year:

2019

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER SIDE RETAINER RH	1		% \$49.20
2	FRONT FENDER RH	1		12, \$579.20
3	FRONT FENDER "HYBRID" EMBLEM RH	1		Ma \$48.60
4	FRONT FENDER INNER SHIELD RH	1		\$175.60
5	FRONT STEEL RIM RH	1		M \$397.80
6	FRONT SUSPENSION SHOCK ABSORBER RH	1		\$498.20
7	FRONT SUSPENSION KNUCKLE ARM RH	1		\$558.90
8	FRONT SUSPENSION WHEEL BEARING RH	11		\$168.20
9	FRONT SUSPENSION LOWER ARM RH	1		5488.80
10	FRONT DOOR RH	1		\$1,184.70
11	FRONT DOOR CHECKER RH	1		\$210.30
12	FRONT DOOR HINGE UPPER RH	1		\$95.10
13	FRONT DOOR HINGE LOWER RH	11		\$95.10
14	FRONT DOOR WEATHERSTRIP RH	1		7
15	FRONT DOOR INNER TRIM BOARD RH	1		\$1,211.20
16	FRONT DOOR REGULATOR RH	1		SVC \$237.10
17	FRONT DOOR REGULATOR MOTOR RH	1		DAM \$747.50
18	FRONT DOOR MECHANISM LOCK RH	11		
19	FRONT DOOR LOCK STRIKER RH	1		\$40.70
20	REAR SLIDING DOOR RH	11		\$1,281.10
21	REAR SLIDING DOOR LOWER GARNISH RH	11		Gr \$135.40
22	REAR SLIDING DOOR MECHANISM LOCK RH	1		\$1,160.50
23	REAR SLIDING DOOR LOCK STRIKER RH	1		/ \$60.10
24	REAR FENDER RH	1		\$1,500.10
25	REAR FENDER LOWER GARNISH RH	1	<u> </u>	\$70.40
26	REAR FENDER INNER SHIELD RH	1	<u> </u>	Fn \$60.90
	/		SUB TOTAL	\$11,834.00
			LESS 25%	-\$2,958.50
			PARTS TOTAL	\$8,875.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	FRONT BUMPER CLIPS	1		ル へ \$50.00
-	FRONT FENDER INNER SHIELD CLIPS RH	1		1n \$30.00
	FRONT TYRE RH - 185/60R15	1		Sea \$180.00
	FRONT DOOR INNER TRIM BOARD CLIPS RH	1		ルハ \$30.00





OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sq

☑ /OptimaWerkz

/OptimaWerkz

Date:

04/02/2022

Vehicle No: SMX9849D

Model:

TOYOTA SIENTA HYBRID

Chassis:

NHP1707177070

2019 Reg.Year:

Third Party Insurer: AIG

SCQ1911P Third Party Veh No:

Date of Accident:

03/02/2022

Estimator:

KIT

Surveyor:

5	REAR DOOR INNER TRIM BOARD CLIPS RH	1		ルル \$30.00
6	REAR FENDER INNER SHIELD CLIPS RH	1		~ \$30.00
			S/N TOTAL	\$350.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST RIGHT ACCIDENT

AREAS & ETC.

FENDER RH

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.

TO TUFF KOTE & UNDERSEAL MATERIALS.

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH & REAR DOOR RH

TO REMOVE & REFIX FRONT WHEEL SUSPENSION ARM & ETC. TO EFFECT ON FRONT

TO WHEEL ALIGNMENT & BALANCING.

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$100.00

\$240.00

ルセ \$150.00

AN \$100.00

\$100.00

\$80.00 20/

\$3,170.00 LABOUR TOTAL

TOTAL

\$12,395.50

LKK Auto Consultants hence net the Repairer of the following: KIT survey belove/s/ler spray painting spley damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repain

