

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

DABSYN CONTRACTOR'S PTE LTD
48 LOWER DELTA ROAD #10-17 THE BEO
CRESCENT
SINGAPORE 160048

Contact : 84375674, 86876742

TAX INVOICE

Repair Code : CLM17092

Date in : 09/02/2022

Vehicle Num. : GBG2779M

Model : TOYOTA DYNA 150 5MT

Chassis/Eng# : JTFAT35Y50K208026/1KD2700475

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR EXHAUST SILENCER PIPE <i>Best</i>	1	618.30	✓ 618.30
REAR EXHAUST SILENCER PIPE RUBBER MOUNTING <i>torn</i>	1	61.10	✓ 61.10
REAR LOWER SIDE STOPPER BRACKET L/R <i>LH torn, RH missing Best</i>	2	98.60	✓ 197.20
REAR LOWER SIDE STOPPER L/R <i>LH torn, RH missing</i>	2	43.10	✓ 86.20
REAR NUMBER PLATE LAMP L/R <i>crack</i>	2	60.70	✓ 121.40
REAR NUMBER PLATE PANEL <i>Best</i>	1	228.60	✓ 228.60
REAR NUMBER PLATE PANEL BRACKET <i>Best</i>	1	57.10	✓ 57.10
REAR SPARE TYRE CARRIER <i>Dented</i>	1	295.30	✓ 295.30
REAR TAILGATE <i>Dented</i>	1	1116.70	✓ 1,116.70
REAR TAILGATE 'TOYOTA' STICKER <i>new</i>	1	238.90	✓ 238.90
REAR TAILGATE HINGES <i>2 pins Best</i>	4	104.00	208 416.00
REAR TAILGATE LOWER PANEL <i>Repair</i>	1	585.80	P. 585.80
REAR TAILLAMP BRACKET L/R <i>Best</i>	2	61.80	✓ 123.60
REAR TAILLAMP L/R <i>cut</i>	2	251.30	✓ 502.60
SIDE GATE FLIP LOCK HANDLE L/R <i>RH Best</i>	2	139.00	139 278.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

DABSYN CONTRACTOR'S PTE LTD
48 LOWER DELTA ROAD #10-17 THE BEO
CRESCENT
SINGAPORE 160048

Contact : 84375674, 86876742

TAX INVOICE

Repair Code : CLM17092

Date in : 09/02/2022

Vehicle Num. : CBG2779M

Model : TOYOTA DYNA 150 5MT

Chassis/Eng# : JTFAT35Y50K208026/1KD2700475

		Subtotal before discount	4,926.80
Percentage discount	20%	3993.40	985.36
		2995.05	
		Sub-total 1	3,941.44
ALUMINIUM PANEL REPAIR KIT - SET	1	150.00	150.00
REAR NUMBER PLATE	1	25.00	25.00
REAR REVERSE SENSOR - SET	1	250.00	250.00
REAR REVERSE SENSOR BRACKET - SET	1	80.00	80.00
REAR STEP BRACKET	1	300.00	300.00
REAR TAILGATE '13PAX' STICKER	1	20.00	20.00
REAR TAILGATE '70KM/H' STICKER	1	20.00	20.00
REAR TAILGATE ALUMINIUM PANEL	1	700.00	700.00
		Subtotal before discount	1,545.00
Percentage discount	0%		0.00
		Sub-total 2	1,545.00
		Parts-total	5,486.44

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

60.00
800.00
120.00
900.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DABSYN CONTRACTOR'S PTE LTD
 48 LOWER DELTA ROAD #10-17 THE BEO
 CRESCENT
 SINGAPORE 160048

Contact : 84375674, 86876742

TAX INVOICE

Repair Code : CLM17092
 Date in : 09/02/2022
 Vehicle Num. : GBG2779M
 Model : TOYOTA DYNA 150 5MT
 Chassis/Eng# : JTFAT35Y50K208026/1KD2700475

To apply anti-rust chemical on repaired and replaced panel.

	1300	60	80.00
Labour Total			1,960.00
Parts & Labour Total			7,446.44

*** This is a computer-generated document which requires no signature.***
 page 3

Adrian Lj
 1/10/02/22

OS Pay
 total: 48000
 L/s: 3.8k ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: